



Approved
CR

Akron Auto Auction
2471 Ley Drive
Akron, OH 44319
3304365819/(330) 773-3921
lbeth@akronautoauction.com
WHOLESALE ASSESSMENT ONLY

Make/Model: 2020
HYUNDAI
IONIQ
HYBRID
4 Door Sedan
Bodystyle/Series: BLUE 4D
HATCHBACK
Color: SILVER
Mileage: 81,599
(Verified, 6
digits)
Turn-in Mileage: -
VIN: KMHC65LC1LU220741
Work Order/
Stock Number: 000928079
Customer: GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalessupport@gsa.gov
Client Stock #: G130703X
Vehicle Grade : Grade 2.2
AutoGrade : 2.2 - Below
Average
Remarks: -
Announcements: • Hail Damage
Certification : Not Certified
Req. Prev. Repair -
Order:



Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	Automatic Transmission	A/C:	Yes
Engine:	4-Cylinder Hybrid	Cruise Control:	Yes
Engine Size:	1.6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	AM/FM Radio	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	Yes
Airbag:	Dual Air Bags	Tilt Steering:	Yes
Seats:	-	Drive Type:	Front Wheel Drive

Equipment

Seat Count: -	Brakes:	Power Brakes
Additional Equipment:		
ABS Brakes	Air Conditioning	Automatic Headlights
Bluetooth Connection	Brake Assist System	Car Tire Size - LR tire size P195/65HR15
Car Tire Size - RR tire size P195/65HR15	Car Tire Size - RF tire size P195/65HR15	Car Tire Size - LF tire size P195/65HR15
Child Safety Locks	Collision Avoidance	Cruise Control
Cylinders - 4	Daytime Running Lights	Driver Air Bag
Empty Weight - 2996 lb	Engine Immobilizer	Floor Mats
Front Wheel Drive	Front Wheel Drive	Independent Climate Control
Intermittent Wipers	Keyless Entry	Keyless Start
LF Tires - 7/32 inch	LR Tires - 6/32 inch	Lane Departure System
MP3 Radio	Master Key - 1key(s)	Motor Fuel Type - Other
Pass-Through Rear Seat	Pass. Air Bag	Power Brakes
Power Lock	Power Mirrors	Power Steering
Power Windows	RF Tires - 7/32 inch	RR Tires - 5/32 inch
Rear Defrost	Rear Spoiler	Reverse Camera
Seat Trim - Cloth	Security System	Side Airbags - Front
Steering Wheel Audio Control	Stereo - AM/FM Radio	Tilt Steering Wheel
Tilt Wheel	Tire Pressure Monitor System	Traction Control
Transmission - Automatic Transmission	Trip Computer	Wheels Front Left - Steel
Wheels Front Right - Steel	Wheels Rear Left - Steel	

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Qtr Panel	Photo Only	Estimate Only	Unknown
	Left Rear Seat	Photo Only	Estimate Only	Unknown
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	Estimate Only	Unknown
	Steering Wheel	Photo Only	Estimate Only	Unknown
	Left Front Tire	Photo Only	Estimate Only	Unknown
	Photo - Rear	Photo Only	Estimate Only	Unknown
	Photo - Front	Photo Only	Estimate Only	Unknown
	Photo - Wheel	Photo Only	Estimate Only	Unknown
	Extra Photo 4	Photo Only	Estimate Only	Unknown
	Photo - Deck	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Right Front Tire	Photo Only	Estimate Only	Unknown
	Overall Picture - Engine	Photo Only	Estimate Only	Unknown
	Extra Photo 2	Photo Only	Estimate Only	Unknown


Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Tire	Photo Only	Estimate Only	Unknown
	Left Rear Tire	Photo Only	Estimate Only	Unknown
	Right Qtr Panel	Photo Only	Estimate Only	Unknown
	Hood	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown
	Roof	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Qtr Panel	Multiple Dents/Paint Damage	Repair	3
	Right Rocker Panel Molding	Chipped	Touch Up	1
	Right Roof	Hail Damage	PDR	6
	Rear Bumper	Chipped	Repair	5
	Roof	Hail Damage	PDR	4
	Right Front Fender	Chipped	Touch Up	1

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rf Mirror Cover	Multiple Scratches Heavy	Touch Up	3
	Right Rear Door	Multiple Dents/Paint Damage	Repair	3
	Warning Light - Engine	On	Report	Unacceptable
	Cowl Cover	Missing	Replace	Replacement Required
	Front Bumper	Curb Rash	Repair	> 12 Inches
	Hood	Chipped	Touch Up	1
	Left Qtr Panel	Hail Damage	PDR	6
	Left Qtr Panel	Multiple Scratches Heavy	Repair	4
	Left Rocker Panel Molding	Chipped	Repair	7
	Left Roof	Hail Damage	PDR	6
	Left Front Door	Multiple Scratches Heavy	Touch Up	3
	Left Front Fender	Multiple Scratches Heavy	Touch Up	2
	Left Rear Door	Multiple Scratches Heavy	Repair	4

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Qtr Panel	Hail Damage	PDR	5

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.