



Approved CR

IAA Portland
4415 NE 158th Avenue
Branch No 308
Portland, OR 97230
(503) 253-1500/(503) 253-9359
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018 RAM
2500**
Bodystyle/Series: **Crew Cab
TRADESMAN
4X4 6'4 BOX**
Color: **White**
Mileage: **33,898
(Verified)**
Turn-in Mileage: **-**
VIN: **3C6TR5CT2JG306689**
Work Order/
Stock Number: **46299172**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G632391V**
Vehicle Grade : **Grade 4.5**
Remarks: **-**
Announcements: **-**
Certification : **-**
Req. Prev. Repair **-**
Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	Yes
Engine:	8-Cylinder Gas	Cruise Control:	No
Engine Size:	5.7 L	Pwr Steering:	Yes
Roof:	Carriage	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /WHITE	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Bench	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - LR 285 / 70 R 17

Car Tire Size - RR 285 / 70 R 17

Car Tire Size - RF 285 / 70 R 17

Car Tire Size - LF 285 / 70 R 17

LF Tires - 10/32 inch

LR Tires - 12/32 inch

RF Tires - 10/32 inch

RR Tires - 12/32 inch

Tire Brand - Front Left - TOYO

Tire Brand - Front Right - TOYO

Tire Brand - Rear Left - TOYO

Tire Brand - Rear Right - TOYO

Tire Model - LF - Open Country H/T

Tire Model - LR - Open Country H/T


Tire Model - RF - Open Country H/T

Tire Model - RR - Open Country H/T

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Aftermarket Accessory	Aftermarket	-	Acceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Roof Panel	Chipped	-	2

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.