



Approved CR

IAA Fargo
4401 37th St. N
Branch No 363
Fargo, ND 58102
(701)552-9731/(701)552-9736
WHOLESALE ASSESSMENT ONLY

Make/Model: **2017
CHEVROLET
SILVERADO
3500HD**

Bodystyle/Series: **- WT**

Color: **Silver**

Mileage: **68,358
(Verified)**

Turn-in Mileage: **-**

VIN: **1GC3KYG8HZ320186**

Work Order/
Stock Number: **46260587**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G630466U**

Vehicle Grade : **Grade 1.6**

Remarks: **-**

Announcements:

**• BED BODY
PANEL AND
TAILGATE
DAMAGE
AND RUST**

Certification : **-**

Req. Prev. Repair **-**

Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Flex Fuel	Cruise Control:	Yes
Engine Size:	6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Bench	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Hydraulic Brakes

Equipment

Additional Equipment:

Car Tire Size - LF 275 / 65 R 18

Car Tire Size - LR 275 / 65 R 18

Car Tire Size - RR 275 / 65 R 18

Car Tire Size - RF 275 / 65 R 18

LF Tires - 16/32 inch

LR Tires - 14/32 inch

RF Tires - 15/32 inch

RR Tires - 15/32 inch

Tire Brand - Front Left - GOODYEAR

Tire Brand - Front Right - GOODYEAR

Tire Brand - Rear Left - GOODYEAR

Tire Brand - Rear Right - GOODYEAR


Tire Model - RR - Wrangler Duratrak RT

Tire Model - RF - Wrangler Duratrak RT


Tire Model - LR - Wrangler Duratrak RT

Tire Model - LF - Wrangler Duratrak RT

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Left Front Fender	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Aftermarket Accessory	Aftermarket	-	Acceptable
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Steering Wheel	Worn	-	Replacement Required
	Left Front Seat Cushion	Torn	-	4 To 5 Inches
	Inside Bed	Multiple Dents/Paint Damage	-	10 Or More

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Tailgate	Severe Damage	-	Replacement Required
	Left Bed Side	Multiple Dents/Paint Damage	-	4
	Cab - Left	Dent(S) W/ Paint Dmg	-	6 To 7 Inches
	Lf Mirror Cover	Broken	-	Replacement Required
	Right Front Door	Heavy Scratch	-	< 1/8 Inch
	Right Cab Side	Dent(S) W/ Paint Dmg	-	< 1/8 Inch

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Bed Side	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Right Tail Light	Broken	-	Replacement Required
	Front Bumper Molding	Bent	-	Replacement Required
	Right Front Fender	Dent(S) W/ Paint Dmg	-	9 To 10 Inches
	Rear Metal Bumper Chrome	Dent(S) W/No Paint Dmg	-	> 12 Inches
	Left Rocker Panel	Rust	-	4 To 5 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rf Lumbar Controls	Missing	-	Replacement Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.