Approved CR

IAA Savannah
348 Commerce Dr.
Branch No 704
Rincon, GA 31326
(912) 826-1219/(912) 826-1387
WHOLESALE ASSESSMENT ONLY

Make/Model:	**2019 CHEVROLET TAHOE**
Bodystyle/Series:	**Sport Utility Vehicle LS**
Color:	**Silver**
Mileage:	**66,112 (Verified)**
Turn-in Mileage:	-
VIN:	**1GNSCAKC3KR348488**
Work Order/ Stock Number:	**46493596**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G421094W**
Vehicle Grade :	**Grade 3.9**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-



Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**8-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**5.3 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth/Vinyl /GRAY**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Buckets**	Drive Type:	**Rear Wheel Drive**
Seat Count:	-	Brakes:	**Air Brakes**

Equipment

Additional Equipment:

Car Tire Size - RR 265 / 65 R 18	Car Tire Size - RF 265 / 65 R 18	Car Tire Size - LF 265 / 65 R 18
Car Tire Size - LR 265 / 65 R 18	LF Tires - 10/32 inch	LR Tires - 10/32 inch
RF Tires - 10/32 inch	RR Tires - 10/32 inch	Tire Brand - Front Left - KELLY
Tire Brand - Front Right - KELLY	Tire Brand - Rear Left - KELLY	Tire Brand - Rear Right - KELLY
Tire Model - LF - Safari Atr	Tire Model - LR - Safari Atr	Tire Model - RF - Safari Atr
Tire Model - RR - Safari Atr		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 4	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Head Lamp	Water Damage	-	Replacement Required
	Front Bumper	Chipped	-	2
	Hitchplate Cover	Missing	-	Replacement Required
	Left Front Door	Dent(S) W/ Paint Dmg	-	1 To 2 Inches
	Right Front Door	Heavy Scratch	-	1/2 To 1 Inch
	Left Front Door	Multiple Scratches Heavy	-	2

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.