Approved CR

IAA Miami-North
20499 Stirling Road
Branch No 736
Southwest Ranch, FL 33332
(954)680-4370/(954)680-4372
WHOLESALE ASSESSMENT ONLY

Make/Model:	**2019 FORD FIESTA**
Bodystyle/Series:	**4 Door Sedan SE**
Color:	**Blue**
Mileage:	**69,812 (Verified)**
Turn-in Mileage:	-
VIN:	**3FADP4BJXKM115334**
Work Order/ Stock Number:	**46493470**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G131331U**
Vehicle Grade :	**Grade 3.3**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-



Drivable: Yes

Equipment

Transmission:	-	A/C:	**No**
Engine:	**4-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**1.6 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /BLACK**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**3rd**	Drive Type:	**Front Wheel Drive**
Seat Count:	-	Brakes:	**Anti Lock Brakes**

Equipment

Additional Equipment:

Car Tire Size - RR 185 / 60 R 15	Car Tire Size - RF 185 / 60 R 15	Car Tire Size - LF 185 / 60 R 15
Car Tire Size - LR 185 / 60 R 15	LF Tires - 7/32 inch	LR Tires - 6/32 inch
RF Tires - 6/32 inch	RR Tires - 5/32 inch	Tire Brand - Front Left - CONTINENTAL
Tire Brand - Front Right - CONTINENTAL	Tire Brand - Rear Left - CONTINENTAL	Tire Brand - Rear Right - CONTINENTAL
Tire Model - RR - Procontact TX	Tire Model - RF - Procontact TX	Tire Model - LR - Procontact TX
Tire Model - LF - Procontact TX		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Bumper	Broken	-	Replacement Required
	Right Head Lamp	Water Damage	-	Replacement Required
	Left Qtr Panel	Dent(S) W/ Paint Dmg	-	1 To 2 Inches
	Left Rear Door	Chipped	-	1
	Left Front Door	Chipped	-	2
	Left Head Lamp	Faded	-	Repair Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Shifter Handle	Worn	-	Replacement Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.