



Approved
CR

Rawls Auto Auction Inc.
2818 Pond Branch Rd.
Leesville, SC 29070
(803) 859-5111/(803) 859-0517
wendyc@rawlsautoauction.com
WHOLESALE ASSESSMENT ONLY

Make/Model: **2017 FORD
F-450 CHASSIS**

Bodystyle/Series: **2 Door Vehicle
XLT**

Color: **WHITE**

Mileage: **97,109 (Verified, 6
digits)**

Turn-in Mileage: **-**

VIN: **1FDUF4HT0HEC47552**

Work Order/
Stock Number: **000378562**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G310214U**

Vehicle Grade : **Grade 3.0**

Remarks: **-**

Announcements:

- AMBULANCE
- POWERSTROKE

Certification : **Not Certified**

Req. Prev. Repair **-**

Order:



Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	Automatic Transmission	A/C:	Yes
Engine:	8-Cylinder Diesel Turbo	Cruise Control:	Yes
Engine Size:	6.7 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	AM/FM CD	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	No
Airbag:	Dual Air Bags	Tilt Steering:	Yes
Seats:	-	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Power Brakes

Equipment





Additional Equipment:

4 Wheel Drive	4 Wheel Drive	ABS Brakes
Adjustable Pedals	Air Conditioning	Automatic Headlights
Auxiliary Pwr Outlet	Bench Seating	Bluetooth Connection
Brake Assist System	CD Player	Car Tire Size - LF tire size LT225/70SR19.5
Car Tire Size - LR tire size LT225/70SR19.5	Car Tire Size - RF tire size LT225/70SR19.5	Car Tire Size - RR tire size LT225/70SR19.5
Cruise Control	Cylinders - 8	Daytime Running Lights
Driver Air Bag	Dual Rear Wheels	Empty Weight - 7183 lb
Engine Immobilizer	Heated Mirrors	Independent Climate Control
Intermittent Wipers	Keyless Entry	LF Tires - 12/32 inch
LR Tires - 10/32 inch	MP3 Radio	Master Key - 2key(s)
Motor Fuel Type - Diesel	Mudflaps	Owner's Manual
Pass. Air Bag	Power Brakes	Power Lock
Power Mirrors	Power Steering	Power Windows
Privacy Glass	RF Tires - 6/32 inch	RR Tires - 7/32 inch
Seat Trim - Cloth	Security System	Side Airbags - Front
Steering Wheel Audio Control	Telematics	Tilt Steering Wheel
Tilt Wheel	Tire Brand - Front Left - LF tire mfg Firestone	Tire Brand - Front Right - RF tire mfg Firestone
Tire Brand - Rear Left - LR tire mfg Bridgestone	Tire Brand - Rear Right - RR tire mfg Firestone	Traction Control
Transmission - Automatic Transmission w/ Overdrive	Trip Computer	Turbocharged
Turn Signal Mirrors	Warranty Books	Wheels Front Left - Steel
Wheels Front Right - Steel	Wheels Rear Left - Steel	Wheels Rear Right - Steel

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Extra Photo 2	Photo Only	Estimate Only	Unknown

Non Chargeable Damages


Photo	Item	Damage	Action	Severity
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Overall Picture - Engine	Photo Only	Estimate Only	Unknown
	Extra Photo 4	Photo Only	Estimate Only	Unknown
	Extra Photo 5	Photo Only	Estimate Only	Unknown
	Extra Photo 1	Photo Only	Estimate Only	Unknown
	Extra Photo 6	Photo Only	Estimate Only	Unknown
	Extra Photo 7	Photo Only	Estimate Only	Unknown
	Extra Photo 8	Photo Only	Estimate Only	Unknown
	Extra Photo 9	Photo Only	Estimate Only	Unknown
	Extra Photo 10	Photo Only	Estimate Only	Unknown
	Photo - Deck	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Roof	Photo Only	Estimate Only	Unknown
	Keys	Photo Only	Estimate Only	Unknown
	Door Panels	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown
	Deck Lid Badge	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Fender	Aftermarket	Report	Acceptable
	Left Front Seat	Torn	Replace	> 12 Inches
	Rear View Mirror	Aftermarket	Report	Acceptable
	Right Front Center Cap	Missing	Replace	Replacement Required
	Right Front Fender	Aftermarket	Report	Acceptable
[no photo]	Maintenance Book	Missing	Replace	Replacement Required
[no photo]	Left Head Lamp	Faded	Refinish	Repair Required
[no photo]	Warranty Book	Missing	Replace	Replacement Required
[no photo]	Owners Manual	Missing	Replace	Replacement Required
[no photo]	Left Front Seat	Stained	Detail	Permanent
[no photo]	Right Head Lamp	Faded	Refinish	Repair Required
[no photo]	Right Front Seat	Stained	Detail	Permanent

Chargeable Damages				
Photo	Item	Damage	Action	Severity
[no photo]	Hood	Chipped	Touch Up	4
[no photo]	Right Front Seat	Worn	Report	Acceptable
	Bluetooth	Clear History	Remove	Removal Required
	Cargo Shelf	Missing	Replace	Replacement Required
	Center Console	Aftermarket	Report	Acceptable
	Front Bumper	Aftermarket	Report	Acceptable
	Grille	Aftermarket	Report	Acceptable
	Headlining	Aftermarket	Report	Acceptable
	Left Bed Side	Multiple Dents/Paint Damage	Repair	2
	Left Front Center Cap	Missing	Replace	Replacement Required
[no photo]	Overall Vehicle	Multiple Scratches Light	Wet Sand	10 Or More

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.