Approved CR

IAA North Virginia
15 Le Way Drive
Branch No 723
Fredericksburg, VA 22406
(540) 373-7800/(540) 371-4123
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2018 RAM 2500**
Bodystyle/Series:	**Crew Cab TRADESMAN 4X4 8` BOX**
Color:	**White**
Mileage:	**25,847 (Verified)**
Turn-in Mileage:	-
VIN:	**3C6TR5HT5JG363607**
Work Order/ Stock Number:	**46503734**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G632772V**
Vehicle Grade :	**Grade 3.8**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-

Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**Yes**
Engine:	**8-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**5.7 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	**AM Radio**	Pwr Windows	**Yes**
Interior - Type/Color:	**Synthetic Leather /GRAY**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Buckets**	Drive Type:	**4-Wheel Drive**
Seat Count:	-	Brakes:	**Disc**

Equipment


Additional Equipment:

Car Tire Size - LF 245 / 70 R 17	Car Tire Size - LR 245 / 70 R 17	Car Tire Size - RR 245 / 70 R 17
Car Tire Size - RF 245 / 70 R 17	LF Tires - 12/32 inch	LR Tires - 9/32 inch
RF Tires - 12/32 inch	RR Tires - 10/32 inch	Tire Brand - Front Left - NATIONAL
Tire Brand - Front Right - NATIONAL	Tire Brand - Rear Left - NATIONAL	Tire Brand - Rear Right - NATIONAL
Tire Model - RR - Commando A/T	Tire Model - RF - Commando A/T	Tire Model - LR - Commando A/T
Tire Model - LF - Commando A/T		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Right Front Fender	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 3	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Tailgate	Heavy Scratch	-	1/2 To 1 Inch
	Front Metal Bumper Painted	Chipped	-	10 Or More
	Right Front Door	Chipped	-	3
	Right Rear Door	Multiple Scratches Heavy	-	2
	Right Bed Side	Heavy Scratch	-	1/8 To 1/2 Inch
	Tailgate Molding	Broken	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Bed Side	Heavy Scratch	-	1 To 2 Inches
	Cab - Left	Heavy Scratch	-	4 To 5 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.