Approved CR

IAA Austin North
23010 Firefly Rd
Branch No 457
Florence, TX 76527
2549700575
mgr-austinnorth@iaai.com
WHOLESALE ASSESSMENT ONLY

Make/Model:	**2012 RAM 2500**
Bodystyle/Series:	**Crew Cab ST**
Color:	**Silver**
Mileage:	**67,387 (Verified)**
Turn-in Mileage:	-
VIN:	**3C6UD5HL3CG143999**
Work Order/ Stock Number:	**46427807**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	-
Vehicle Grade :	**Grade 2.5**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-



Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**6-Cylinder Diesel**	Cruise Control:	**Yes**
Engine Size:	**6.7 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Leather Interior /GRAY**	Rear Defroster:	**No**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**5th**	Drive Type:	**4-Wheel Drive**
Seat Count:	-	Brakes:	**Disc**

Equipment

Additional Equipment:

Car Tire Size - LF 245 / 70 R 17	Car Tire Size - LR 245 / 70 R 17	Car Tire Size - RR 245 / 70 R 17
Car Tire Size - RF 245 / 70 R 17	LF Tires - 7/32 inch	LR Tires - 4/32 inch
RF Tires - 6/32 inch	RR Tires - 11/32 inch	Tire Brand - Front Left - IRONMAN
Tire Brand - Front Right - IRONMAN	Tire Brand - Rear Left - IRONMAN	Tire Brand - Rear Right - IRONMAN
Tire Model - RF - All Country AT2	Tire Model - LR - All Country AT2	Tire Model - LF - All Country AT2
Tire Model - RR - All Country AT2		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Right Front Fender	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Tonneau Cover	Aftermarket	-	Acceptable
	Warning - Tire Pressure	On	-	Unacceptable

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Warning Light - Engine	On	-	Unacceptable

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Grille	Chipped	-	8
	Hood	Dent(S) W/ Paint Dmg	-	2 To 3 Inches
	Right Front Wheel	Corrosion	-	> 12 Inches
	Right Rear Wheel	Mismatched	-	Replacement Required
	Spare Wheel	Corrosion	-	> 12 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Metal Bumper Painted	Dent(S) W/ Paint Dmg	-	7 To 8 Inches
	Tailgate	Multiple Dents/Paint Damage	-	3
	Left Rear Wheel	Corrosion	-	> 12 Inches
	Left Front Wheel	Corrosion	-	> 12 Inches
	Inside Bed	Multiple Scratches Heavy	-	10 Or More
	Front Metal Bumper Painted	Chipped	-	4

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.