



Approved CR

America's Auto Auction - Pensacola, Inc  
 6615 Mobile Highway  
 Pensacola, FL 32526-1264  
 850-972-8601/(850) 944-8482  
 Della.Smith@AmericasAutoAuction.com  
 WHOLESALE ASSESSMENT ONLY

Make/Model: **2018 FORD  
FUSION  
HYBRID**

Bodystyle/Series: **4 Door  
Vehicle S 4D  
SEDAN**

Color: **BLUE**

Mileage: **60,323  
(Verified, 6  
digits)**

Turn-in Mileage: **-**

VIN: **3FA6P0UU7JR235909**

Work Order/  
Stock Number: **000355754**

Customer: **GSA Fleet Vehicle Sales  
1800 F Street NW  
Washington, DC 20405  
fleetsalesupport@gsa.gov**

Client Stock #: **G101452V**

Vehicle Grade : **Grade 4.1**

Remarks: **-**

Announcements: **-**

Certification : **Not Certified**

Req. Prev. Repair **-**

Order:



Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

### Equipment

|                        |                               |                 |                          |
|------------------------|-------------------------------|-----------------|--------------------------|
| Transmission:          | <b>Automatic Transmission</b> | A/C:            | <b>Yes</b>               |
| Engine:                | <b>4-Cylinder Hybrid</b>      | Cruise Control: | <b>Yes</b>               |
| Engine Size:           | <b>2 L</b>                    | Pwr Steering:   | <b>Yes</b>               |
| Roof:                  | <b>Hard Top</b>               | Pwr Locks:      | <b>Yes</b>               |
| Radio:                 | <b>AM/FM CD</b>               | Pwr Windows     | <b>Yes</b>               |
| Interior - Type/Color: | <b>Cloth Interior /GRAY</b>   | Rear Defroster: | <b>Yes</b>               |
| Airbag:                | <b>Dual Air Bags</b>          | Tilt Steering:  | <b>Yes</b>               |
| Seats:                 | <b>-</b>                      | Drive Type:     | <b>Front Wheel Drive</b> |
| Seat Count:            | <b>-</b>                      | Brakes:         | <b>Power Brakes</b>      |

## Equipment


### Additional Equipment:

|                                                    |                                              |                                            |
|----------------------------------------------------|----------------------------------------------|--------------------------------------------|
| 4th Passenger Door                                 | ABS Brakes                                   | Air Conditioning                           |
| Automatic Headlights                               | Auxiliary Pwr Outlet                         | Bluetooth Connection                       |
| Brake Assist System                                | CD Player                                    | Car Tire Size - RR tire size P225/50VR17   |
| Car Tire Size - LF tire size P225/50VR17           | Car Tire Size - LR tire size P225/50VR17     | Car Tire Size - RF tire size P225/50VR17   |
| Child Safety Locks                                 | Cruise Control                               | Cylinders - 4                              |
| Daytime Running Lights                             | Driver Air Bag                               | Dual Air Conditioning                      |
| Empty Weight - 3615 lb                             | Engine Immobilizer                           | Floor Mats                                 |
| Front Wheel Drive                                  | Front Wheel Drive                            | Independent Climate Control                |
| Intermittent Wipers                                | Keyless Entry                                | Keyless Start                              |
| LF Tires - 6/32 inch                               | LR Tires - 6/32 inch                         | MP3 Radio                                  |
| Master Key - 1key(s)                               | Motor Fuel Type - Other                      | Pass. Air Bag                              |
| Power Brakes                                       | Power Lock                                   | Power Mirrors                              |
| Power Steering                                     | Power Trunk/Liftgate                         | Power Windows                              |
| Privacy Glass                                      | RF Tires - 6/32 inch                         | RR Tires - 6/32 inch                       |
| Rear Defrost                                       | Remote Trunk Release                         | Reverse Camera                             |
| Seat Trim - Cloth                                  | Security System                              | Side Airbags - Front                       |
| Steering Wheel Audio Control                       | Telematics                                   | Tilt Steering Wheel                        |
| Tire Brand - Front Left - LF tire mfg Kumho        | Tire Brand - Front Right - RF tire mfg Kumho | Tire Brand - Rear Left - LR tire mfg Kumho |
| Tire Brand - Rear Right - RR tire mfg Kumho        | Tire Pressure Monitor System                 | Traction Control                           |
| Transmission - Automatic Transmission w/ Overdrive | Trip Computer                                | Wheels Front Left - Aluminium              |
| Wheels Front Right - Aluminium                     | Wheels Rear Left - Aluminium                 | Wheels Rear Right - Aluminium              |


## Non Chargeable Damages

| Photo                                                                               | Item                   | Damage     | Action        | Severity |
|-------------------------------------------------------------------------------------|------------------------|------------|---------------|----------|
|  | Photo - Vin/Id Sticker | Photo Only | Estimate Only | Unknown  |
|  | Stereo                 | Photo Only | Estimate Only | Unknown  |


### Non Chargeable Damages

| Photo                                                                               | Item             | Damage     | Action        | Severity |
|-------------------------------------------------------------------------------------|------------------|------------|---------------|----------|
|    | Extra Photo 4    | Photo Only | Estimate Only | Unknown  |
|    | Extra Photo 5    | Photo Only | Estimate Only | Unknown  |
|    | Left Rear Seat   | Photo Only | Estimate Only | Unknown  |
|    | Roof             | Photo Only | Estimate Only | Unknown  |
|    | Keys             | Photo Only | Estimate Only | Unknown  |
|    | Door Panels      | Photo Only | Estimate Only | Unknown  |
|  | Left Front Tire  | Photo Only | Estimate Only | Unknown  |
|  | Right Front Tire | Photo Only | Estimate Only | Unknown  |
|  | Right Rear Tire  | Photo Only | Estimate Only | Unknown  |
|  | Photo - Rear     | Photo Only | Estimate Only | Unknown  |
|  | Left Rear Tire   | Photo Only | Estimate Only | Unknown  |
|  | Deck Lid Badge   | Photo Only | Estimate Only | Unknown  |
|  | Extra Photo 2    | Photo Only | Estimate Only | Unknown  |

### Non Chargeable Damages

| Photo                                                                             | Item                       | Damage     | Action        | Severity |
|-----------------------------------------------------------------------------------|----------------------------|------------|---------------|----------|
|  | Extra Photo 1              | Photo Only | Estimate Only | Unknown  |
|  | Photo - Interior           | Photo Only | Estimate Only | Unknown  |
|  | Photo - Dash               | Photo Only | Estimate Only | Unknown  |
|  | Overall Picture - Odometer | Photo Only | Estimate Only | Unknown  |
|  | Photo - Wheel              | Photo Only | Estimate Only | Unknown  |
|  | Extra Photo 3              | Photo Only | Estimate Only | Unknown  |

### Chargeable Damages

| Photo                                                                               | Item                      | Damage                   | Action | Severity   |
|-------------------------------------------------------------------------------------|---------------------------|--------------------------|--------|------------|
|  | Deck Lid                  | Multiple Scratches Light | Report | 5          |
|  | Front Bumper              | Chipped                  | Report | 3          |
|  | Hood                      | Chipped                  | Report | 10 Or More |
|  | Left Front Door           | Multiple Scratches Light | Report | 2          |
|  | Left Front Fender         | Multiple Scratches Light | Report | 3          |
|  | Left Front Mirror Housing | Chipped                  | Report | 2          |

| Chargeable Damages                                                                  |                   |                          |        |               |
|-------------------------------------------------------------------------------------|-------------------|--------------------------|--------|---------------|
| Photo                                                                               | Item              | Damage                   | Action | Severity      |
|    | Left Front Seat   | Stained                  | Report | Permanent     |
|    | Left Rear Door    | Multiple Scratches Light | Report | 3             |
|    | Left Rear Seat    | Stained                  | Report | Permanent     |
|    | Rear Bumper       | Multiple Scratches Light | Report | 5             |
|    | Right Front Seat  | Stained                  | Report | Permanent     |
|   | Right Front Wheel | Curb Rash                | Report | 5 To 6 Inches |
|  | Right Rear Seat   | Stained                  | Report | Permanent     |
|  | Seat Center Rear  | Stained                  | Report | Permanent     |
| [no photo]                                                                          | Oil               | Low Fluid                | Report | Unacceptable  |

**File Insurance Claim? - Additional Damages and Remarks: -**

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.