



Approved
CR

IAA Syracuse
8459 Brewerton Road
Branch No 628
Cicero, NY 13039
(315) 699-2622/(315) 699-5481
WHOLESALE ASSESSMENT ONLY

Make/Model: **2019 FORD F-250**
Bodystyle/Series: **Regular Cab XL**
Color: **Brown**
Mileage: **78,413 (Verified)**
Turn-in Mileage: **-**
VIN: **1FTBF2B68KED43729**
Work Order/
Stock Number: **46326554**
Customer: **GSA Fleet Vehicle Sales**
1800 F Street NW
Washington, DC 20405
fleetsalessupport@gsa.gov

Client Stock #: **G632603V**

Vehicle Grade : **Grade 2.5**

Remarks: **-**

Announcements:

- repairs may be needed
- ANNOUNCEMENTS:
Warning indicator on
- please check OBDII
report on IAA site.
- /Rust

Certification : **-**

Req. Prev. Repair **-**

Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Gas	Cruise Control:	Yes
Engine Size:	6.2 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Leather Interior /-	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - RR 285 / 70 R 17

Car Tire Size - RF 285 / 70 R 17

Car Tire Size - LF 285 / 70 R 17

Car Tire Size - LR 285 / 70 R 17

LF Tires - 13/32 inch

LR Tires - 10/32 inch

RF Tires - 10/32 inch

RR Tires - 8/32 inch

Tire Brand - Front Left - IRONMAN

Tire Brand - Front Right - IRONMAN

Tire Brand - Rear Left - IRONMAN

Tire Brand - Rear Right - IRONMAN

Tire Model - LF - All Country M/T

Tire Model - LR - All Country M/T

Tire Model - RF - All Country M/T

Tire Model - RR - All Country M/T

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Extra Photo 7	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Warning - Tire Pressure	On	-	Unacceptable
	Warning Light - Engine	On	-	Unacceptable

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Door	Multiple Scratches Light	-	5
	Right Front Wheel	Corrosion	-	> 12 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Bed Side	Dent(S) W/ Paint Dmg	-	1 To 2 Inches
	Right Rear Wheel	Corrosion	-	> 12 Inches
	Rear Metal Bumper Chrome	Dent(S) W/No Paint Dmg	-	5 To 6 Inches
	Tailgate	Chipped	-	3
	Left Rear Wheel	Corrosion	-	> 12 Inches
	Aftermarket Accessory	Aftermarket	-	Acceptable

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Front Wheel	Corrosion	-	9 To 10 Inches
	Steering Wheel	Worn	-	Replacement Required
	Left Front Seat Cushion	Torn	-	7 To 8 Inches
	Left Drip Rail	Multiple Scratches Heavy	-	2
	Left Bed Side	Dent(S) W/ Paint Dmg	-	5 To 6 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.