Original CR

IAA Honolulu
91-445A Komohana St
Branch No 114
Kapolei, HI 96707
(808) 682-2858/(808) 682-3988
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2017 CHRYSLER PACIFICA HYBRID**
Bodystyle/Series:	**Van TOURING PLUS**
Color:	**Blue**
Mileage:	**13,038 (Verified)**
Turn-in Mileage:	-
VIN:	**2C4RC1H7XHR836194**
Work Order/ Stock Number:	**46524072**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G414459U**
Vehicle Grade :	**Grade 3.9**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-

Drivable: Yes

Equipment

Transmission:	**Continuously Variable Transmission**	A/C:	**No**
Engine:	**6-Cylinder Hybrid**	Cruise Control:	**Yes**
Engine Size:	**3.6 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /GRAY**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Power - Driver Only**	Drive Type:	**Front Wheel Drive**
Seat Count:	-	Brakes:	**Hydraulic Brakes**

Equipment

Additional Equipment:

Car Tire Size - LF 235 / 65 R 17	Car Tire Size - LR 235 / 65 R 17	Car Tire Size - RR 235 / 65 R 17
Car Tire Size - RF 235 / 65 R 17	LF Tires - 9/32 inch	LR Tires - 8/32 inch
RF Tires - 11/32 inch	RR Tires - 8/32 inch	Tire Brand - Front Left - TOYO
Tire Brand - Front Right - TOYO	Tire Brand - Rear Left - TOYO	Tire Brand - Rear Right - TOYO
Tire Model - RR - Extensa A/S Ii	Tire Model - RF - Extensa A/S Ii	Tire Model - LR - Extensa A/S Ii
Tire Model - LF - Extensa A/S Ii		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Dash	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Wheel	Curb Rash	-	1/2 To 1 Inch
	Hood	Multiple Scratches Light	-	3
	Rear Bumper	Multiple Scratches Heavy	-	2
	Lift Gate	Chipped	-	3
	Left Rear Door	Chipped	-	2

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Door	Chipped	-	1
	Roof	Chipped	-	4
	Left Qtr Panel	Multiple Scratches Heavy	-	2
	Right Front Door	Heavy Scratch	-	1/2 To 1 Inch

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.