



Approved CR

IAA Kansas City
2663 S 88th Street
Branch No 527
Kansas City, KS 66111
(913) 422-9303/(913) 422-7421
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018 DODGE JOURNEY**
Bodystyle/Series: **Sport Utility Vehicle SXT**
Color: **Silver**
Mileage: **60,834 (Verified)**
Turn-in Mileage: **-**
VIN: **3C4PDCBG2JT324781**
Work Order/ Stock Number: **46257030**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G410166U**
Vehicle Grade : **Grade 2.0**
Remarks: **-**
Announcements:

**• HAIL
DAMAGE**

Certification : **-**
Req. Prev. Repair Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Flex Fuel	Cruise Control:	Yes
Engine Size:	3.6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth/Vinyl /-	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	3rd	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - LR 225 / 65 R 17	Car Tire Size - RR 225 / 65 R 17	Car Tire Size - RF 225 / 65 R 17
Car Tire Size - LF 225 / 65 R 17	LF Tires - 9/32 inch	LR Tires - 4/32 inch
RF Tires - 5/32 inch	RR Tires - 4/32 inch	Tire Brand - Front Left - COOPER
Tire Brand - Front Right - PERFORMER	Tire Brand - Rear Left - PERFORMER	Tire Brand - Rear Right - PERFORMER
Tire Model - LF - Endeavor Plus	Tire Model - LR - Performer CXV Sport	Tire Model - RF - Performer CXV Sport
Tire Model - RR - Performer CXV Sport		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Right Front Fender	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 3	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Warning - Tire Pressure	On	-	Unacceptable
	Rear Seats	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Door	Multiple Dents/No Paint Damage	-	2
	Left Front Fender	Multiple Dents/No Paint Damage	-	2
	Rear Bumper	Chipped	-	4

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Door	Multiple Dents/Paint Damage	-	3
	Left Drip Rail	Multiple Dents/No Paint Damage	-	3
	Right Drip Rail	Multiple Dents/No Paint Damage	-	3
	Left Head Lamp	Water Damage	-	Replacement Required
	Roof	Hail Damage	-	10 Or More
	Right Front Fender	Multiple Dents/No Paint Damage	-	2

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Wheel	Curb Rash	-	1/2 To 1 Inch
	Hood	Hail Damage	-	10 Or More
	Front Bumper	Chipped	-	3

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.