



Approved CR

IAA Des Moines
1000 Armstrong Dr
Branch No 536
De Soto, IA 50069
(515)823-0600/(515)823-0626
WHOLESALE ASSESSMENT ONLY

Make/Model: **2023
HYUNDAI
KONA**

Bodystyle/Series: **Sport Utility
Vehicle SE**

Color: **Gray**

Mileage: **103,417
(Verified)**

Turn-in Mileage: **-**

VIN: **KM8K2CAB9PU013073**

Work Order/
Stock Number: **46292031**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G61-A0465**

Vehicle Grade : **Grade 4.1**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Continuously Variable Transmission	A/C:	No
Engine:	4-Cylinder Gas	Cruise Control:	No
Engine Size:	2 L	Pwr Steering:	No
Roof:	-	Pwr Locks:	No
Radio:	-	Pwr Windows	No
Interior - Type/Color:	- /BLACK	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	No
Seats:	-	Drive Type:	All Wheel Drive
Seat Count:	-	Brakes:	-


Equipment

Additional Equipment:

Car Tire Size - LF 205 / 60 R 16	Car Tire Size - LR 205 / 60 R 16	Car Tire Size - RR 205 / 60 R 16
Car Tire Size - RF 205 / 60 R 16	LF Tires - 5/32 inch	LR Tires - 6/32 inch
RF Tires - 4/32 inch	RR Tires - 7/32 inch	Tire Brand - Front Left - SENTURY
Tire Brand - Front Right - SENTURY	Tire Brand - Rear Left - SENTURY	Tire Brand - Rear Right - SENTURY
Tire Model - RR - Sentury Touring	Tire Model - RF - Sentury Touring	Tire Model - LR - Sentury Touring
Tire Model - LF - Sentury Touring		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Rear Bumper/Cover	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Rear Wheel	Curb Rash	-	1/2 To 1 Inch
	Lift Gate	Chipped	-	2
	Front Bumper Cover Upper	Chipped	-	2
	Right Front Wheel	Curb Rash	-	1/8 To 1/2 Inch

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.