Approved CR

IAA North Virginia
15 Le Way Drive
Branch No 723
Fredericksburg, VA 22406
(540) 373-7800/(540) 371-4123
WHOLESALE ASSESSMENT ONLY

Make/Model:	**2018 FORD TRANSIT CONNECT**
Bodystyle/Series:	**Wagon XL**
Color:	**Navy**
Mileage:	**31,399 (Verified)**
Turn-in Mileage:	-
VIN:	**NM0GE9E79J1343179**
Work Order/ Stock Number:	**46468867**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G41A6250**
Vehicle Grade :	**Grade 2.9**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-



Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**4-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**2.5 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /BLACK**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Buckets**	Drive Type:	**Front Wheel Drive**
Seat Count:	-	Brakes:	**Disc**

Equipment

Additional Equipment:

Car Tire Size - LF 215 / 55 R 16	Car Tire Size - LR 215 / 55 R 16	Car Tire Size - RR 215 / 55 R 16
Car Tire Size - RF 215 / 55 R 16	LF Tires - 6/32 inch	LR Tires - 7/32 inch
RF Tires - 8/32 inch	RR Tires - 7/32 inch	Tire Brand - Front Left - MAVIS
Tire Brand - Front Right - MAVIS	Tire Brand - Rear Left - MAVIS	Tire Brand - Rear Right - MAVIS
Tire Model - RR - All Season Highway Touring	Tire Model - RF - All Season Highway Touring	Tire Model - LR - All Season Highway Touring
Tire Model - LF - All Season Highway Touring		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Steering Wheel	Worn	-	Replacement Required
	Left Front Wheel Cover	Curb Rash	-	1 To 2 Inches
	Left Front Fender	Multiple Scratches Heavy	-	10 Or More
	Left Front Door	Multiple Scratches Heavy	-	10 Or More
	Right Front Fender	Dent(S) W/ Paint Dmg	-	1/2 To 1 Inch
	Right Head Lamp	Faded	-	Repair Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Head Lamp	Faded	-	Repair Required
	Front Bumper Cover Upper	Oxidized	-	> 12 Inches
	Left Front Door	De-Identify	-	Removal Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.