



Approved CR

IAA Indianapolis
3302 South Harding Street
Branch No 541
Indianapolis, IN 46217
(317) 787-3202/(317)783-0586
WHOLESALE ASSESSMENT ONLY

Make/Model: **2007
CHEVROLET
SILVERADO
1500**

Bodystyle/Series: **- WORK
TRUCK**

Color: **White**

Mileage: **55,997
(Verified)**

Turn-in Mileage: **-**

VIN: **1GCEK14067Z582062**

Work Order/
Stock Number: **46426140**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G62B2385**

Vehicle Grade : **Grade 1.0**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission w/ Overdrive	A/C:	No
Engine:	8-Cylinder Flex Fuel	Cruise Control:	Yes
Engine Size:	5.3 L	Pwr Steering:	Yes
Roof:	Coach	Pwr Locks:	No
Radio:	-	Pwr Windows	No
Interior - Type/Color:	Cloth/Vinyl /GRAY	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Bench	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - LR 245 / 70 R 17

Car Tire Size - RR 245 / 70 R 17

Car Tire Size - RF 245 / 70 R 17

Car Tire Size - LF 245 / 70 R 17

LF Tires - 3/32 inch

LR Tires - 3/32 inch

RF Tires - 3/32 inch

RR Tires - 3/32 inch

Tire Brand - Front Left - MASTERCRAFT

Tire Brand - Front Right - MASTERCRAFT

Tire Brand - Rear Left - MASTERCRAFT

Tire Brand - Rear Right - MASTERCRAFT

Tire Model - LF - Courser C/T

Tire Model - LR - Courser C/T


Tire Model - RF - Courser C/T

Tire Model - RR - Courser C/T

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Warning Light - Engine	On	-	Unacceptable
	Frame	Rust	-	Severe Damage
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Tire	Worn	-	Replacement Required
	Right Rear Tire	Worn	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Bed Side	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Left Bed Side	Rust	-	> 12 Inches
	Rear Bumper	Missing	-	Replacement Required
	Rear Bumper Reinforcement	Missing	-	Replacement Required
	Right Front Fender	Heavy Scratch	-	5 To 6 Inches
	Hood	Chipped	-	1

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Cab Side	Rust	-	Severe Damage
	Cab - Left	Rust	-	Severe Damage
	Left Front Door	Heavy Scratch	-	1/8 To 1/2 Inch
	Front Left Bumper/Cover	Heavy Scratch	-	9 To 10 Inches
	Roof	Chipped	-	10 Or More
	Steering Wheel	Worn	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Tire	Worn	-	Replacement Required
	Right Front Tire	Worn	-	Replacement Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.