



Approved CR

IAA Austin North
23010 Firefly Rd
Branch No 457
Florence, TX 76527
2549700575
mgr-austinnorth@iaai.com
WHOLESALE ASSESSMENT ONLY

Make/Model: **2011 FORD
F-750**
Bodystyle/Series: **- XL/XLT**
Color: **White**
Mileage: **18,121
(Verified)**
Turn-in Mileage: **-**
VIN: **3FRWF7FG8BV589821**
Work Order/
Stock Number: **46382397**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **-**
Vehicle Grade : **Grade 3.9**
Remarks: **-**
Announcements: **-**
Certification : **-**
Req. Prev. Repair **-**
Order: **-**



Drivable: Yes

Equipment

Transmission:	-	A/C:	No
Engine:	6-Cylinder Diesel	Cruise Control:	Yes
Engine Size:	6.7 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	No
Radio:	-	Pwr Windows	No
Interior - Type/Color:	Leather Interior /GRAY	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	3rd	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Air Brakes

Equipment

Additional Equipment:

Car Tire Size - LF 295 / 75 R 22.5	Car Tire Size - LR 295 / 75 R 22.5	Car Tire Size - RR 295 / 75 R 22.5
Car Tire Size - RF 295 / 75 R 22.5	LF Tires - 19/32 inch	LR Tires - 16/32 inch
RF Tires - 19/32 inch	RR Tires - 15/32 inch	Tire Brand - Front Left - BRIDGESTONE
Tire Brand - Front Right - BRIDGESTONE	Tire Brand - Rear Left - BRIDGESTONE	Tire Brand - Rear Right - HANKOOK
Tire Model - RR - AH12	Tire Model - RF - Ecopia R268	Tire Model - LR - Ecopia R268
Tire Model - LF - Ecopia R268		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Odometer	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Instrument Panel	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Headlamp Mounting Panel	Chipped	-	2
	Right Rear Wheel	Curb Rash	-	> 12 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Lift Gate	Multiple Scratches Light	-	3
	Left Rear Wheel	Corrosion	-	> 12 Inches
	Left Running Board	Dent(S) W/ Paint Dmg	-	1 To 2 Inches
	Left Front Wheel	Corrosion	-	> 12 Inches
	Right Front Wheel	Corrosion	-	> 12 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.