Approved CR

IAA Des Moines
1000 Armstrong Dr
Branch No 536
De Soto, IA 50069
(515)823-0600/(515)823-0626
WHOLESALE ASSESSMENT ONLY

Make/Model:	**2017 FORD F-450**
Bodystyle/Series:	**Crew Cab XL**
Color:	**Silver**
Mileage:	**86,267 (Verified)**
Turn-in Mileage:	-
VIN:	**1FT8W4DT5HED81047**
Work Order/ Stock Number:	**45751423**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G71-0207U**
Vehicle Grade :	**Grade 2.5**
Remarks:	-
Announcements:	• Hail Damage
Certification :	-
Req. Prev. Repair Order:	-



Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**8-Cylinder Diesel**	Cruise Control:	**No**
Engine Size:	**6.7 L**	Pwr Steering:	**No**
Roof:	-	Pwr Locks:	**No**
Radio:	-	Pwr Windows	**No**
Interior - Type/Color:	- **/GRAY**	Rear Defroster:	**No**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**No**
Seats:	-	Drive Type:	**4-Wheel Drive**
Seat Count:	-	Brakes:	-

Equipment

Additional Equipment:

Car Tire Size - RR 225 / 70 R 19.5	Car Tire Size - RF 225 / 70 R 19.5	Car Tire Size - LF 225 / 70 R 19.5
Car Tire Size - LR 225 / 70 R 19.5	LF Tires - 16/32 inch	LR Tires - 12/32 inch
RF Tires - 15/32 inch	RR Tires - 12/32 inch	Tire Brand - Front Left - COOPER
Tire Brand - Front Right - COOPER	Tire Brand - Rear Left - COOPER	Tire Brand - Rear Right - COOPER
Tire Model - LF - Work Series Asd	Tire Model - LR - Work Series Asd	Tire Model - RF - Work Series Asd
Tire Model - RR - Work Series Asd		


Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Qtr Flare	Heavy Scratch	-	> 12 Inches
	Left Bed Side	Dent(S) W/ Paint Dmg	-	6 To 7 Inches
	Right Head Lamp	Faded	-	Repair Required
	Inside Bed	Heavy Scratch	-	> 12 Inches
	Right Rear Seat Cushion	Stained	-	Permanent

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Seat Cushion	Stained	-	Permanent
	Left Front Wheel	Corrosion	-	> 12 Inches
	Left Head Lamp	Faded	-	Repair Required
	Left Rear Wheel	Corrosion	-	> 12 Inches
	Right Rear Wheel	Corrosion	-	> 12 Inches
	Front Metal Bumper Chrome	Dent(S) W/No Paint Dmg	-	1 To 2 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Hood	Peeling	-	2 To 3 Inches
	Rear Bumper Step Pad	Broken	-	Replacement Required
	Tailgate	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Tailgate Protective Cap	Missing	-	Replacement Required
	Right Qtr Flare	Heavy Scratch	-	6 To 7 Inches
	R Cab Corner Panel	Dent(S) W/ Paint Dmg	-	1/8 To 1/2 Inch

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.