



Approved
CR

IAA Pulaski
1250 East Main Street
Branch No 724
Pulaski, VA 24301
(540) 994-6490/(540) 994-6495
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018 FORD
TRANSIT CONNECT**
Bodystyle/Series: **Cargo Van XL**
Color: **White**
Mileage: **14,490 (Verified)**
Turn-in Mileage: -
VIN: **NM0LE7E78J1340390**
Work Order/
Stock Number: **46369971**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalessupport@gsa.gov**
Client Stock #: **G410808U**
Vehicle Grade : **Grade 3.6**
Remarks: -
Announcements: **• ANNOUNCEMENTS:**
Certification : -
Req. Prev. Repair -
Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	4-Cylinder Gas	Cruise Control:	Yes
Engine Size:	2.5 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth/Vinyl /BLACK	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - RR 215 / 65 R 16	Car Tire Size - RF 215 / 65 R 16	Car Tire Size - LF 215 / 65 R 16
Car Tire Size - LR 215 / 65 R 16	LF Tires - 8/32 inch	LR Tires - 8/32 inch
RF Tires - 8/32 inch	RR Tires - 8/32 inch	Tire Brand - Front Left - HANKOOK
Tire Brand - Front Right - HANKOOK	Tire Brand - Rear Left - HANKOOK	Tire Brand - Rear Right - HANKOOK
Tire Model - LF - Kinergy ST (H735)	Tire Model - LR - Kinergy ST (H735)	Tire Model - RF - Kinergy ST (H735)
Tire Model - RR - Kinergy ST (H735)		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
[no photo]	Personally Identifiable Info	De-Identify	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Lift Gate	Chipped	-	3

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Door	Light Scratch	-	1/2 To 1 Inch
	Left Front Fender	Dent(S) W/No Paint Dmg	-	1 To 2 Inches
	Left Front Seat Molding	Broken	-	Replacement Required
	Vinyl Floor	Torn	-	5 To 6 Inches
	Right Front Fender	Dent(S) W/ Paint Dmg	-	1/2 To 1 Inch
	Left Head Lamp	Faded	-	Repair Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Head Lamp	Faded	-	Repair Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.