



Approved CR

America's Auto Auction - Pensacola, Inc
 6615 Mobile Highway
 Pensacola, FL 32526-1264
 850-972-8601/(850) 944-8482
 Della.Smith@AmericasAutoAuction.com
 WHOLESALE ASSESSMENT ONLY

Make/Model: **2021 GMC TERRAIN**
4 Door Sport Utility
 Bodystyle/Series: **Vehicle SLE 4D SUV AWD**
 Color: **BLACK**
 Mileage: **67,930 (Verified, 6 digits)**
 Turn-in Mileage: **-**
 VIN: **3GKALTEV4ML381284**
 Work Order/ Stock Number: **000355138**
 Customer: **GSA Fleet Vehicle Sales
 1800 F Street NW
 Washington, DC 20405
 fleetsalesupport@gsa.gov**
 Client Stock #: **G610357Y**
 Vehicle Grade : **Grade 3.0**
 Remarks: **window replacement approved
 \$350 10/14**
 Announcements: **-**
 Certification : **Not Certified**
 Req. Prev. Repair Order: **-**



Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	Automatic Transmission	A/C:	Yes
Engine:	4-Cylinder Gas Turbo	Cruise Control:	Yes
Engine Size:	1.5 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	AM/FM Radio	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	No
Airbag:	Dual Air Bags	Tilt Steering:	No
Seats:	-	Drive Type:	All Wheel Drive


Equipment

Seat Count:	-	Brakes:	Power Brakes
Additional Equipment:			
ABS Brakes	Air Conditioning	All Wheel Drive	
Automatic Headlights	Auxiliary Pwr Outlet	Bluetooth Connection	
Car Tire Size - RR tire size P225/65R17	Car Tire Size - RF tire size P225/65R17	Car Tire Size - LR tire size P225/65R17	
Car Tire Size - LF tire size P225/65R17	Collision Avoidance	Cruise Control	
Cylinders - 4	Daytime Running Lights	Driver Air Bag	
Electrochromic Rearview Mirror	Empty Weight - 3622 lb	Floor Mats	
HID Headlights	Heated Mirrors	Keyless Entry	
Keyless Start	LF Tires - 5/32 inch	LR Tires - 7/32 inch	
Lane Departure System	Leather Steering Wheel	MP3 Radio	
Master Key - 1key(s)	Motor Fuel Type - Gas	Pass-Through Rear Seat	
Pass. Air Bag	Power Brakes	Power Lock	
Power Mirrors	Power Windows	Privacy Glass	
RF Tires - 5/32 inch	RR Tires - 7/32 inch	Reverse Camera	
Seat Trim - Cloth	Security System	Side Airbags - Front	
Spare Tire	Steering Wheel Audio Control	Stereo - AM/FM Radio	
Telematics	Tire Brand - Front Left - LF tire mfg Bridgestone	Tire Brand - Front Right - RF tire mfg Bridgestone	
Tire Brand - Rear Left - LR tire mfg Hankook	Tire Brand - Rear Right - RR tire mfg Bridgestone	Tire Pressure Monitor System	
Traction Control	Transmission - Automatic Transmission	Trip Computer	
Turbocharged	Wheels Front Left - Aluminium	Wheels Front Right - Aluminium	
Wheels Rear Left - Aluminium	Wheels Rear Right - Aluminium		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Seat	Photo Only	Estimate Only	Unknown
	Roof	Photo Only	Estimate Only	Unknown
	Keys	Photo Only	Estimate Only	Unknown


Non Chargeable Damages


Photo	Item	Damage	Action	Severity
	Door Panels	Photo Only	Estimate Only	Unknown
	Left Front Tire	Photo Only	Estimate Only	Unknown
	Right Front Tire	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Photo - Dash	Photo Only	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Photo - Wheel	Photo Only	Estimate Only	Unknown
	Extra Photo 4	Photo Only	Estimate Only	Unknown
	Right Rear Tire	Photo Only	Estimate Only	Unknown
	Photo - Rear	Photo Only	Estimate Only	Unknown
	Left Rear Tire	Photo Only	Estimate Only	Unknown
	Deck Lid Badge	Photo Only	Estimate Only	Unknown
	Stereo	Photo Only	Estimate Only	Unknown

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	Estimate Only	Unknown
	Extra Photo 1	Photo Only	Estimate Only	Unknown
	Extra Photo 3	Photo Only	Estimate Only	Unknown
	Extra Photo 5	Photo Only	Estimate Only	Unknown
	Photo - Vin/Id Sticker	Photo Only	Estimate Only	Unknown

Chargeable Damages

Photo	Item	Damage	Action	Severity
[no photo]	Oil	Low Fluid	Report	Unacceptable
[no photo]	Battery	Inoperable	Report	Repair Required
	Front Bumper	Multiple Scratches Light	Report	3
	Hood	Chipped	Report	10 Or More
	Left Qtr Panel	Chipped	Report	2
	Lift Gate	Multiple Scratches Heavy	Report	2
	Left Front Door	Multiple Dents/Paint Damage	Report	2
	Left Front Fender	Multiple Dents/Paint Damage	Report	2

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Rear Door	Multiple Dents/Paint Damage	Report	2
	Right Qtr Panel	Multiple Scratches Light	Report	4
	Rear Bumper	Multiple Scratches Light	Report	5
	Roof	Chipped	Report	9
	Right Front Door	Multiple Scratches Light	Report	3
	Right Front Fender	Multiple Scratches Light	Report	2
	Right Rear Door	Multiple Dents/No Paint Damage	Report	2
	Windshield	Cracked	Report	2 To 3 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.