Approved CR

IAA Shreveport
4836 McGee Rd
Branch No 434
Greenwood, LA 71033
(318) 938-5108/(318) 938-5838
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2018 FORD F-350**
Bodystyle/Series:	**Crew Cab XL**
Color:	**White**
Mileage:	**44,894 (Verified)**
Turn-in Mileage:	-
VIN:	**1FT8W3B6XJEC83855**
Work Order/ Stock Number:	**46414095**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G63-2066V**
Vehicle Grade :	**Grade 4.1**
Remarks:	-
Announcements:	• windshield cracked
Certification :	-
Req. Prev. Repair Order:	-

Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**8-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**6.2 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Vinyl Interior /GRAY**	Rear Defroster:	**No**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Bench**	Drive Type:	**4-Wheel Drive**
Seat Count:	-	Brakes:	**Disc**

Equipment


Additional Equipment:

Car Tire Size - LF 245 / 75 R 17	Car Tire Size - LR 245 / 75 R 17	Car Tire Size - RR 245 / 75 R 17
Car Tire Size - RF 245 / 75 R 17	LF Tires - 8/32 inch	LR Tires - 8/32 inch
RF Tires - 8/32 inch	RR Tires - 8/32 inch	Tire Brand - Front Left - BFGOODRICH
Tire Brand - Front Right - BFGOODRICH	Tire Brand - Rear Left - BFGOODRICH	Tire Brand - Rear Right - BFGOODRICH
Tire Model - RR - All-Terrain T/A Ko	Tire Model - RF - All-Terrain T/A Ko	Tire Model - LR - All-Terrain T/A Ko
Tire Model - LF - All-Terrain T/A		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Keys	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Side Panel	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Windshield	Cracked	-	> 12 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	L Cab Side Molding	Gouged	-	1/2 To 1 Inch

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.