



Approved CR

IAA Macon
2200 Trade Ave.
Branch No 734
Macon, GA 31217
(478) 314-0031/(478) 314-0040
WHOLESALE ASSESSMENT ONLY

Make/Model: **2020 FORD
TRANSIT-350
PASSENGER
VAN**

Bodystyle/Series: **Wagon XL**

Color: **Red**

Mileage: **95,430
(Verified)**

Turn-in Mileage: **-**

VIN: **1FBAX2Y80LKB08881**

Work Order/
Stock Number: **46267930**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G432350X**

Vehicle Grade : **Grade 2.5**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Gas	Cruise Control:	Yes
Engine Size:	3.5 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth/Vinyl /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - RR 235 / 65 R 16	Car Tire Size - LF 235 / 65 R 16	Car Tire Size - RF 235 / 65 R 16
Car Tire Size - LR 235 / 65 R 16	LF Tires - 11/32 inch	LR Tires - 6/32 inch
RF Tires - 11/32 inch	RR Tires - 6/32 inch	Tire Brand - Front Left - FIRESTONE
Tire Brand - Front Right - FIRESTONE	Tire Brand - Rear Left - FIRESTONE	Tire Brand - Rear Right - FIRESTONE
Tire Model - RR - Transforce CV2	Tire Model - RF - Transforce CV2	Tire Model - LR - Transforce CV2
Tire Model - LF - Transforce CV2		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Wheel	Curb Rash	-	1/2 To 1 Inch
	Left Rear Cargo Door	Dent(S) W/No Paint Dmg	-	6 To 7 Inches
	R Bumper Textured	Misaligned	-	Repair Required
	Left Rear Wheel	Corrosion	-	2 To 3 Inches
	Left Front Wheel	Curb Rash	-	1 To 2 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Roof	Multiple Dents/No Paint Damage	-	3
	Right Rear Seat Cushion	Torn	-	1/2 To 1 Inch
	Right Rear Carpet	Torn	-	> 12 Inches
	Steering Wheel	Worn	-	Replacement Required
	Right Rear Door	Multiple Scratches Light	-	3
	Rear Ls Panel	Dent(S) W/No Paint Dmg	-	7 To 8 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Cargo Door	Dent(S) W/No Paint Dmg	-	5 To 6 Inches
	Hood	Dent(S) W/ Paint Dmg	-	1 To 2 Inches
	Right Rear Wheel	Curb Rash	-	6 To 7 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.