



Approved CR

IAA Charleston  
430 Tannenbaum Rd  
Branch No 720  
Ravenel, SC 29470  
(843) 556-7620/(843) 571-3006  
WHOLESALE ASSESSMENT ONLY

Make/Model: **2019 DODGE  
CHARGER**  
4 Door Sedan  
Bodystyle/Series: **POLICE  
RWD**  
Color: **Gray**  
Mileage: **63,733  
(Verified)**  
Turn-in Mileage: -  
VIN: **2C3CDXAG4KH736464**  
Work Order/  
Stock Number: **46418667**  
Customer: **GSA Fleet Vehicle Sales  
1800 F Street NW  
Washington, DC 20405  
fleetsalesupport@gsa.gov**  
Client Stock #: **G110528W**  
Vehicle Grade : **Grade 4.1**  
Remarks: -  
Announcements: -  
Certification : -  
Req. Prev. Repair -  
Order: -



Drivable: Yes

### Equipment

|                        |                               |                 |                         |
|------------------------|-------------------------------|-----------------|-------------------------|
| Transmission:          | <b>Automatic Transmission</b> | A/C:            | <b>No</b>               |
| Engine:                | <b>6-Cylinder Flex Fuel</b>   | Cruise Control: | <b>Yes</b>              |
| Engine Size:           | <b>3.6 L</b>                  | Pwr Steering:   | <b>Yes</b>              |
| Roof:                  | <b>Hard Top</b>               | Pwr Locks:      | <b>Yes</b>              |
| Radio:                 | -                             | Pwr Windows     | <b>Yes</b>              |
| Interior - Type/Color: | <b>Cloth Interior /BLACK</b>  | Rear Defroster: | <b>Yes</b>              |
| Airbag:                | <b>Driver Side Air Bag</b>    | Tilt Steering:  | <b>Yes</b>              |
| Seats:                 | <b>Buckets</b>                | Drive Type:     | <b>Rear Wheel Drive</b> |
| Seat Count:            | -                             | Brakes:         | <b>Disc</b>             |

## Equipment

### Additional Equipment:

Car Tire Size - RR 225 / 60 R 18

Car Tire Size - RF 225 / 60 R 18

Car Tire Size - LF 225 / 60 R 18

Car Tire Size - LR 225 / 60 R 18

LF Tires - 7/32 inch

LR Tires - 8/32 inch

RF Tires - 8/32 inch

RR Tires - 6/32 inch

Tire Brand - Front Left - FIRESTONE

Tire Brand - Front Right - FIRESTONE

Tire Brand - Rear Left - FIRESTONE

Tire Brand - Rear Right - FIRESTONE

Tire Model - RR - Firehawk As

Tire Model - RF - Firehawk As


Tire Model - LR - Firehawk As

Tire Model - LF - Firehawk As

## Non Chargeable Damages

| Photo                                                                               | Item                    | Damage     | Action | Severity |
|-------------------------------------------------------------------------------------|-------------------------|------------|--------|----------|
|    | Rear Seats              | Photo Only | -      | -        |
|    | Extra Photo 1           | Photo Only | -      | -        |
|   | Photo - Dash            | Photo Only | -      | -        |
|  | Right Rear Bumper/Cover | Photo Only | -      | -        |
|  | Left Rear Bumper/Cover  | Photo Only | -      | -        |
|  | Left Front Fender       | Photo Only | -      | -        |
|  | Extra Photo 5           | Photo Only | -      | -        |
|  | Extra Photo 4           | Photo Only | -      | -        |

### Non Chargeable Damages

| Photo                                                                               | Item               | Damage     | Action | Severity |
|-------------------------------------------------------------------------------------|--------------------|------------|--------|----------|
|    | Right Front Fender | Photo Only | -      | -        |
|    | Extra Photo 3      | Photo Only | -      | -        |
|    | Extra Photo 2      | Photo Only | -      | -        |
|    | Rear Bumper        | Photo Only | -      | -        |
|    | Instrument Panel   | Photo Only | -      | -        |
|   | Left Side Panel    | Photo Only | -      | -        |
|  | Right Side Panel   | Photo Only | -      | -        |
|  | Front Cover Center | Photo Only | -      | -        |
|  | Keys               | Photo Only | -      | -        |
|  | Odometer           | Photo Only | -      | -        |
|  | Engine             | Photo Only | -      | -        |

| Non Chargeable Damages                                                             |                         |               |        |                 |
|------------------------------------------------------------------------------------|-------------------------|---------------|--------|-----------------|
| Photo                                                                              | Item                    | Damage        | Action | Severity        |
|   | Photo - Vin/Id Sticker  | Photo Only    | -      | -               |
|   | Warning - Tire Pressure | On            | -      | Unacceptable    |
| Chargeable Damages                                                                 |                         |               |        |                 |
| Photo                                                                              | Item                    | Damage        | Action | Severity        |
|   | Left Rear Door          | Heavy Scratch | -      | > 12 Inches     |
|  | Right Front Fender      | Heavy Scratch | -      | 1/8 To 1/2 Inch |

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.