



Approved CR

IAA San Diego
2380 Britannia Blvd
Branch No 116
San Diego, CA 92154
(619) 710-2866/(619) 710-2878
WHOLESALE ASSESSMENT ONLY

Make/Model: **2015 FORD
F-450**
Bodystyle/Series: **Crew Cab XL**
Color: **White**
Mileage: **37,668
(Verified)**
Turn-in Mileage: **-**
VIN: **1FT8W4DT2FEB26093**
Work Order/
Stock Number: **46258150**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G710532Z**
Vehicle Grade : **Grade 3.1**
Remarks: **-**
Announcements: **-**
Certification : **-**
Req. Prev. Repair **-**
Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Diesel	Cruise Control:	Yes
Engine Size:	6.7 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Bench	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment


Additional Equipment:

Car Tire Size - LF 225 / 70 R 19.5	Car Tire Size - LR 225 / 70 R 19.5	Car Tire Size - RR 225 / 70 R 19.5
Car Tire Size - RF 225 / 70 R 19.5	LF Tires - 18/32 inch	LR Tires - 18/32 inch
RF Tires - 18/32 inch	RR Tires - 18/32 inch	Tire Brand - Front Left - HANKOOK
Tire Brand - Front Right - HANKOOK	Tire Brand - Rear Left - HANKOOK	Tire Brand - Rear Right - HANKOOK
Tire Model - RR - DH07	Tire Model - RF - DH07	Tire Model - LR - DH07
Tire Model - LF - DH07		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Keys	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Fender	Photo Only	-	-
[no photo]	Personally Identifiable Info	De-Identify	-	-
	Extra Photo 6	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Engine	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Metal Bumper Painted	Multiple Dents/Paint Damage	-	2
	Tailgate	Dent(S) W/ Paint Dmg	-	1/2 To 1 Inch
	Tailgate Protective Cap	Missing	-	Replacement Required
	Left Qtr Flare	Multiple Scratches Heavy	-	2

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Wheel	Corrosion	-	> 12 Inches
	Left Front Door	Heavy Scratch	-	1/2 To 1 Inch
	Left Front Wheel	Corrosion	-	2 To 3 Inches
	Right Rear Seat Cushion	Torn	-	3 To 4 Inches
	Windshield	Chipped	-	1/8 To 1/2 Inch
	Steering Wheel	Worn	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Wheel	Corrosion	-	> 12 Inches
	Right Front Wheel	Corrosion	-	9 To 10 Inches
	Front Metal Bumper Painted	Chipped	-	10 Or More
	Right Head Lamp	Faded	-	Repair Required
	Left Head Lamp	Faded	-	Repair Required
	Left Bed Side	Chipped	-	3

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.