Approved CR

Dealers Auto Auction of Cincinnati, LLC
120 City Centre Drive
Cincinnati, OH 45216
513-679-7910/513-679-7913
aschoenling@dealersauto.com
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2020 FORD EXPEDITION**
Bodystyle/Series:	**Sport Utility Vehicle XL**
Color:	**BLACK**
Mileage:	**87,215 (Digital)**
Turn-in Mileage:	-
VIN:	**1FMJU1GT0LEA40774**
Work Order/ Stock Number:	**0051559**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**102620I2A40774**
Vehicle Grade :	**Grade 4.4**
Remarks:	-
Announcements:	• As Is • AS IS
Certification :	**Not Certified**
Req. Prev. Repair Order:	-

Drivable: Yes

As Is 100K Miles: NO

Equipment

Transmission:	**Automatic Transmission w/ Overdrive**	A/C:	**Yes**
Engine:	**6-Cylinder Gas Turbo**	Cruise Control:	**Yes**
Engine Size:	**3.5 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	- **/BLACK**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**No**
Seats:	**Buckets**	Drive Type:	**4-Wheel Drive**
Seat Count:	**0**	Brakes:	**Power Brakes**

Equipment

Additional Equipment:

4th Passenger Door	Automatic Headlights	Auxiliary Audio Input
Auxiliary Pwr Outlet	Backup camera and monitor	Blind Spot Monitor
Bluetooth Connection	Brake Assist System	Car LF Tires - 11/32 inch
Car LR Tires - 10/32 inch	Car RF Tires - 11/32 inch	Car RR Tires - 10/32 inch
Car Tire Size - LF: P275/65TR18 LR: P275/65TR18 RF: P275/65TR18 RR: P275/65TR18	Child Safety Locks	Cross - Traffic Alert
Cylinders - 6	Daytime Running Lights	Driver Adjustable Lumbar
Driver Illuminated Vanity Mirr	Driver Restriction Features	Driver Vanity Mirror
Electronic Stability Control	Engine Immobilizer	Floor Mats
Fog Lamps	Forward Collision Alert System	Front Head Air Bag
Front Tow Hooks	Heated Mirrors	Ignition Key - 2key(s)
Independent Climate Control	Intermittent Wipers	Keyless Start
LF Tires - 11/32 inch	LR Tires - 10/32 inch	Lane Departure System
Leather Steering Wheel	Misc. Special Features - Passenger Third Door, Airbag Disconnect Switch, Automatic Highbeams, Driver Monitoring, Rear Collisi	Pass. Air Bag
Passenger Air Bag Sensor	Passenger Illuminated Vanity M	Passenger Vanity Mirror
Power Driver Seat	Power Mirrors	Privacy Glass
RF Tires - 11/32 inch	RR Tires - 10/32 inch	Rear AC
Rear Bench Seat	Rear Head Air Bag	Running Board
Security System	Side Airbags - Front	Smart Device Integration
Steering Wheel Audio Control	Telematics	Tilt Steering Wheel
Tire Brand - Front Left - GOODYEAR	Tire Brand - Front Right - GOODYEAR	Tire Brand - Rear Left - GOODYEAR
Tire Brand - Rear Right - GOODYEAR	Tire LF - 11/32 inch	Tire Pressure Monitor System
Tire RF - 11/32 inch	Tire Size - LF: P275/65TR18 LR: P275/65TR18 RF: P275/65TR18 RR: P275/65TR18	Tire Size - LF: P275/65TR18 LR: P275/65TR18 RF: P275/65TR18 RR: P275/65TR18
Tow Hitch	Transmission - Automatic Transmission	Transmission - Automatic Transmission w/ Overdrive
Trip Computer	Wheels Front Left - Aluminium	Wheels Front Right - Aluminium
Wheels Rear Left - Aluminium	Wheels Rear Right - Aluminium	WiFi Hotspot

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-


Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 6	Photo Only	-	-
	Extra Photo 7	Photo Only	-	-
	Extra Photo 8	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Extra Photo 9	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Miscellaneous	Photo Only	-	-
	Miscellaneous	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Door	Dent(S) W/No Paint Dmg	PDR	Pdr-1 Dent
	Right Rear Door	Chipped	Touch Up	1
	Right Front Door	Chipped	Touch Up	3
[no photo]	Turbo	Noise	Mechanical Check	Repair Required
[no photo]	Transmission	Vibration	Mechanical Check	Repair Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.