Approved CR

IAA Colorado Springs
8500 Import Ct
Branch No 377
Colorado Springs, CO 80925
(719) 755-0862/(719) 715-0988
mgr-coloradosprings@iaai.com
WHOLESALE ASSESSMENT ONLY




| | |
|---|---|
| Make/Model: | **2018 CHEVROLET SILVERADO 2500HD** |
| Bodystyle/Series: | **Crew Cab WT** |
| Color: | **Silver** |
| Mileage: | **88,980 (Verified)** |
| Turn-in Mileage: | - |
| VIN: | **1GC1KUEG0JF237663** |
| Work Order/ Stock Number: | **45680469** |
| Customer: | GSA Fleet Vehicle Sales<br>1800 F Street NW<br>Washington, DC 20405<br>fleetsalessupport@gsa.gov |
| Client Stock #: | **G63-0651V** |
| Vehicle Grade : | **Grade 2.4** |
| Remarks: | - |
| Announcements: | • WINDSHIELD CRACKED, DAMAGE DRIVER SIDE REAR BED PANEL |
| Certification : | - |
| Req. Prev. Repair Order: | - |

Drivable: Yes

## Equipment

| | | | |
|---|---|---|---|
| Transmission: | **Automatic Transmission** | A/C: | **No** |
| Engine: | **8-Cylinder Flex Fuel** | Cruise Control: | **Yes** |
| Engine Size: | **6 L** | Pwr Steering: | **Yes** |
| Roof: | **Hard Top** | Pwr Locks: | **Yes** |
| Radio: | - | Pwr Windows | **Yes** |
| Interior - Type/Color: | **Cloth Interior /GRAY** | Rear Defroster: | **No** |
| Airbag: | **Driver Side Air Bag** | Tilt Steering: | **Yes** |

## Equipment

| | | | |
|---|---|---|---|
| Seats: | **Bench** | Drive Type: | **4-Wheel Drive** |
| Seat Count: | - | Brakes: | **Disc** |


Additional Equipment:

| | | |
|---|---|---|
| Car Tire Size - LF 265 / 70 R 17 | Car Tire Size - LR 265 / 70 R 17 | Car Tire Size - RR 265 / 70 R 17 |
| Car Tire Size - RF 265 / 70 R 17 | LF Tires - 4/32 inch | LR Tires - 4/32 inch |
| RF Tires - 4/32 inch | RR Tires - 4/32 inch | Tire Brand - Front Left - HANKOOK |
| Tire Brand - Front Right - HANKOOK | Tire Brand - Rear Left - HANKOOK | Tire Brand - Rear Right - HANKOOK |
| Tire Model - RR - Dynapro AT2 Xtreme RF12 | Tire Model - RF - Dynapro AT2 Xtreme RF12 | Tire Model - LR - Dynapro AT2 Xtreme RF12 |
| Tire Model - LF - Dynapro AT2 Xtreme RF12 | | |

## Non Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Odometer | Photo Only | - | - |
|  | Rear Seats | Photo Only | - | - |
|  | Warning Light - Wrench | On | - | Unacceptable |
|  | Photo - Vin/Id Sticker | Photo Only | - | - |
|  | Engine | Photo Only | - | - |
|  | Keys | Photo Only | - | - |

## Non Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Front Cover Center | Photo Only | - | - |
|  | Right Side Panel | Photo Only | - | - |
|  | Left Side Panel | Photo Only | - | - |
|  | Instrument Panel | Photo Only | - | - |
|  | Rear Bumper | Photo Only | - | - |
|  | Extra Photo 2 | Photo Only | - | - |
|  | Extra Photo 3 | Photo Only | - | - |
|  | Right Front Fender | Photo Only | - | - |
|  | Extra Photo 4 | Photo Only | - | - |
|  | Extra Photo 5 | Photo Only | - | - |
|  | Extra Photo 6 | Photo Only | - | - |

## Non Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Left Front Fender | Photo Only | - | - |
|  | Left Rear Bumper/Cover | Photo Only | - | - |
|  | Right Rear Bumper/Cover | Photo Only | - | - |
|  | Photo - Dash | Photo Only | - | - |
|  | Extra Photo 1 | Photo Only | - | - |

## Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Right Rear Door | Heavy Scratch | - | 1 To 2 Inches |
|  | Right Front Wheel | Curb Rash | - | 1/2 To 1 Inch |
|  | Right Rear Wheel | Curb Rash | - | 5 To 6 Inches |

## Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Rear Metal Bumper Chrome | Dent(S) W/No Paint Dmg | - | 1 To 2 Inches |
|  | Left Bed Side | Dent(S) W/ Paint Dmg | - | > 12 Inches |
|  | Left Rear Wheel | Curb Rash | - | 3 To 4 Inches |
|  | Left Front Fender | Dent(S) W/ Paint Dmg | - | 1 To 2 Inches |
|  | Left Front Wheel | Curb Rash | - | 1 To 2 Inches |
|  | Windshield | Cracked | - | > 12 Inches |

## Chargeable Damages

| Photo | Item | Damage | Action | Severity |
|---|---|---|---|---|
|  | Hood | Dent(S) W/ Paint Dmg | - | 1/2 To 1 Inch |
|  | Left Front Door | Multiple Scratches Light | - | 5 |
|  | Left Rear Door | Multiple Scratches Light | - | 6 |
|  | Right Bed Side | Multiple Dents/Paint Damage | - | 3 |
|  | Tailgate | Dent(S) W/ Paint Dmg | - | 1/2 To 1 Inch |
|  | Tailgate Protective Cap | Broken | - | Replacement Required |

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.