



Approved
CR

Perryopolis Auto Auction
3447 Pittsburgh Rd
PO Box 445
Perryopolis, PA 15473
724-736-4445/727-736-0466
jacob@perryautoauction.com
WHOLESALE ASSESSMENT ONLY

2020
CHEVROLET
Make/Model: SILVERADO
MEDIUM
DUTY
Bodystyle/Series: Incomplete
Truck 0
Color: WHITE
Mileage: 93,374
(Verified, 6
digits)
Turn-in Mileage: -
VIN: 1HTKHPVH0LH629369
Work Order/
Stock Number: 000308000
Customer: GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov
Client Stock #: G71-0537X
Vehicle Grade : Grade 3.5
Remarks: -

Announcements:

• DEFICIENCIES,
WHEN
KNOWN, HAVE
BEEN NOTED
IN THE ITEM
DESCRIPTION;
HOWEVER,
• THE ABSENCE
OF ANY
INDICATED
DEFICIENCIES
DOES NOT
MEAN THERE
ARE NONE
• LIFTGATE
WILL NOT
OPEN
COMPLETELY

Certification : Not Certified
Req. Prev. Repair -
Order:



Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Diesel	Cruise Control:	No
Engine Size:	6.6 L	Pwr Steering:	No
Roof:	Hard Top	Pwr Locks:	No
Radio:	-	Pwr Windows	No
Interior - Type/Color:	- / GRAY	Rear Defroster:	No
Airbag:	-	Tilt Steering:	No
Seats:	-	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	-

Additional Equipment:

LR Tires - 18/32 inch

Tire Brand - Front Left - LF TIRE MFG
Generic

Tire Brand - Front Right - RF TIRE MFG
Generic

Tire Brand - Rear Left - LR TIRE MFG
Generic

Tire Brand - Rear Right - RR TIRE MFG
Generic

Two-Wheel Drive

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Overall Picture - Engine	Photo Only	Estimate Only	Unknown
	Photo - Front	Photo Only	Estimate Only	Unknown
	Photo - Right	Photo Only	Estimate Only	Unknown
	Photo - Left	Photo Only	Estimate Only	Unknown
	Photo - Wheel	Photo Only	Estimate Only	Unknown
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Vin Plate	Photo Only	Estimate Only	Unknown

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Miscellaneous	Photo Only	Estimate Only	Unknown
	Warning Light - Emissions	Photo Only	Estimate Only	Unknown
	Liftgate Support	Bent	Report	Unknown
	Lift Gate	Rust	Report	Permanent
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Frame	Photo Only	Estimate Only	Unknown

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.