Approved CR

IAA Lincoln
301 Madigan Dr
Branch No 509
Lincoln, IL 62656
(217) 732-8555/(217) 732-7555
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2020 HYUNDAI IONIQ HYBRID**
Bodystyle/Series:	**4 Door Hatch Back BLUE**
Color:	**White**
Mileage:	**73,753 (Verified)**
Turn-in Mileage:	-
VIN:	**KMHC65LC9LU232023**
Work Order/ Stock Number:	**46485442**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G133768X**
Vehicle Grade :	**Grade 4.1**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-

Drivable: Yes

Equipment

Transmission:	-	A/C:	**No**
Engine:	**4-Cylinder Hybrid**	Cruise Control:	**Yes**
Engine Size:	**1.6 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth/Vinyl /GRAY**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Buckets**	Drive Type:	**Front Wheel Drive**
Seat Count:	-	Brakes:	**Disc**

Equipment

Additional Equipment:

Car Tire Size - RR 195 / 65 R 15	Car Tire Size - RF 195 / 65 R 15	Car Tire Size - LF 195 / 65 R 15
Car Tire Size - LR 195 / 65 R 15	LF Tires - 5/32 inch	LR Tires - 8/32 inch
RF Tires - 5/32 inch	RR Tires - 8/32 inch	Tire Brand - Front Left - MILESTAR
Tire Brand - Front Right - MILESTAR	Tire Brand - Rear Left - MILESTAR	Tire Brand - Rear Right - MILESTAR
Tire Model - LF - MS932 Sport	Tire Model - LR - MS932 Sport	Tire Model - RF - MS932 Sport
Tire Model - RR - MS932 Sport		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Right Front Fender	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Fender	Dent(S) W/ Paint Dmg	-	< 1/8 Inch
	Right Front Wheel Cover	Curb Rash	-	6 To 7 Inches
	Front Bumper	Chipped	-	10 Or More
	Right Qtr Panel	Dent(S) W/ Paint Dmg	-	< 1/8 Inch

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.