Approved CR

IAA Charlotte
1710 Starita Rd
Branch No 714
Charlotte, NC 28206
(704) 596-5854/(704) 596-7492
WHOLESALE ASSESSMENT ONLY

Make/Model:	**2021 NISSAN ALTIMA**
Bodystyle/Series:	**4 Door Sedan S FWD**
Color:	**White**
Mileage:	**56,059 (Verified)**
Turn-in Mileage:	-
VIN:	**1N4BL4BV9MN347261**
Work Order/ Stock Number:	**46485669**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G101046X**
Vehicle Grade :	**Grade 4.0**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-



Drivable: Yes

Equipment

Transmission:	**Continuously Variable Transmission**	A/C:	**No**
Engine:	**4-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**2.5 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth/Vinyl /BLACK**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Buckets**	Drive Type:	**Front Wheel Drive**
Seat Count:	-	Brakes:	**Disc**

Equipment

Additional Equipment:

Car Tire Size - RR 215 / 60 R 16	Car Tire Size - RF 215 / 60 R 16	Car Tire Size - LF 215 / 60 R 16
Car Tire Size - LR 215 / 60 R 16	LF Tires - 7/32 inch	LR Tires - 9/32 inch
RF Tires - 8/32 inch	RR Tires - 8/32 inch	Tire Brand - Front Left - SUREDRIVE
Tire Brand - Front Right - SUREDRIVE	Tire Brand - Rear Left - SUREDRIVE	Tire Brand - Rear Right - SUREDRIVE
Tire Model - LF - touring a/s	Tire Model - LR - touring a/s	Tire Model - RF - touring a/s
Tire Model - RR - touring a/s		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Left Front Fender	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Side Panel	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Bumper	Chipped	-	3
	Right Front Fender	Multiple Scratches Heavy	-	2
	Right Front Wheel Cover	Curb Rash	-	1/2 To 1 Inch
	Right Rear Wheel Cover	Curb Rash	-	1 To 2 Inches
	Deck Lid	Chipped	-	2

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Door	Heavy Scratch	-	1 To 2 Inches
	Windshield	Multiple Chips	-	2
	Hood	Chipped	-	4

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.