



Approved CR

IAA Denver East
8510 Brighton Rd.
Branch No 374
Commerce City, CO 80022
(303) 287-9737/(303) 287-1214
WHOLESALE ASSESSMENT ONLY

Make/Model: **2019 FORD
F-250**

Bodystyle/Series: **Crew Cab XL**

Color: **White**

Mileage: **106,214
(Verified)**

Turn-in Mileage: **-**

VIN: **1FT7W2B61KEE75446**

Work Order/
Stock Number: **46326718**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G631634W**

Vehicle Grade : **Grade 1.8**

Remarks: **-**

Announcements:

- HAIL DAMAGE
- PASSENGER SIDE BODY AND DOOR DAMAGED. FRONT PASSENGER SIDE GLASS CRACKED

Certification : **-**

Req. Prev. Repair **-**

Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Gas	Cruise Control:	Yes
Engine Size:	6.2 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Leather Interior /GRAY	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes

Equipment

Seats:	3rd	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Disc

Additional Equipment:

Car Tire Size - RR 245 / 75 R 17	Car Tire Size - RF 245 / 75 R 17	Car Tire Size - LF 245 / 75 R 17
Car Tire Size - LR 245 / 75 R 17	LF Tires - 8/32 inch	LR Tires - 3/32 inch
RF Tires - 7/32 inch	RR Tires - 3/32 inch	Tire Brand - Front Left - BFGOODRICH
Tire Brand - Front Right - BFGOODRICH	Tire Brand - Rear Left - MICHELIN	Tire Brand - Rear Right - BFGOODRICH
Tire Model - LF - All-Terrain T/A KO2	Tire Model - LR - LTX M/S2	Tire Model - RF - All-Terrain T/A KO2
Tire Model - RR - All-Terrain T/A KO2		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rr Door Panel Trim/Mld	Missing	-	Replacement Required
	Left Rear Tire	Worn	-	Replacement Required
	Roof Panel	Hail Damage	-	10 Or More
	Tailgate	Dent(S) W/No Paint Dmg	-	Pdr-1 Dent

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Bed Side	Dent(S) W/No Paint Dmg	-	> 12 Inches
	Right Rear Door Molding	Missing	-	Replacement Required
	Right Rear Door	Dent(S) W/ Paint Dmg	-	11 To 12 Inches
	Right Front Door	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Front Metal Bumper Chrome	Multiple Dents/No Paint Damage	-	3
	Hood	Hail Damage	-	10 Or More

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Door Glass	Broken	-	Replacement Required
	Right Rear Tire	Worn	-	Replacement Required
	Left Front Seat	Torn	-	4 To 5 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.