



Approved CR

IAA Billings
75 Cerise Road
Branch No 361
Billings, MT 59101
(406) 259-2377/(406) 259-2302
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018 FORD EXPLORER**
Bodystyle/Series: **Sport Utility Vehicle -**
Color: **Silver**
Mileage: **98,430 (Verified)**
Turn-in Mileage: **-**
VIN: **1FM5K8B80JGC77530**
Work Order/
Stock Number: **46339652**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G62-3387V**
Vehicle Grade : **Grade 3.9**
Remarks: **-**
Announcements: **-**
Certification : **-**
Req. Prev. Repair **-**
Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Gas	Cruise Control:	Yes
Engine Size:	3.5 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	No
Seats:	3rd	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - RR 245 / 60 R 18

Car Tire Size - RF 245 / 60 R 18

Car Tire Size - LF 245 / 60 R 18

Car Tire Size - LR 245 / 60 R 18

LF Tires - 5/32 inch

LR Tires - 5/32 inch

RF Tires - 5/32 inch

RR Tires - 6/32 inch

Tire Brand - Front Left - NOKIAN

Tire Brand - Front Right - NOKIAN

Tire Brand - Rear Left - NOKIAN

Tire Brand - Rear Right - NOKIAN

Tire Model - LF - Nokian One

Tire Model - LR - Nokian One

Tire Model - RF - Nokian One

Tire Model - RR - Nokian One

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 4	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Fender	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Hood	Dent(S) W/ Paint Dmg	-	2 To 3 Inches
	Right Front Seat Cushion	Stained	-	Permanent
	Right Qtr Panel	Multiple Dents/No Paint Damage	-	Pdr-2 Dents
	Right Rear Door	Dent(S) W/No Paint Dmg	-	Pdr-1 Dent

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.