



Approved
CR

IAA North Virginia
15 Le Way Drive
Branch No 723
Fredericksburg, VA 22406
(540) 373-7800/(540) 371-4123
WHOLESALE ASSESSMENT ONLY

Make/Model: **2015 FORD F-450 CHASSIS**
Bodystyle/Series: **Crew Cab XL**
Color: **Navy**
Mileage: **55,604 (Verified)**
Turn-in Mileage: **-**
VIN: **1FD9W4HT3FEB26050**
Work Order/
Stock Number: **46423890**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G71A0033**
Vehicle Grade : **Grade 3.6**
Remarks: **-**
Announcements: **• ANNOUNCEMENTS:**
Certification : **-**
Req. Prev. Repair **-**
Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	Yes
Engine:	8-Cylinder Diesel	Cruise Control:	Yes
Engine Size:	6.7 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - RR 225 / 70 R 19.5

Car Tire Size - RF 225 / 70 R 19.5

Car Tire Size - LF 225 / 70 R 19.5

Car Tire Size - LR 225 / 70 R 19.5

LF Tires - 12/32 inch

LR Tires - 12/32 inch

RF Tires - 12/32 inch

RR Tires - 12/32 inch

Tire Brand - Front Left - SYNERGY

Tire Brand - Front Right - SYNERGY

Tire Brand - Rear Left - SYNERGY

Tire Brand - Rear Right - SYNERGY

Tire Model - LF - SP900

Tire Model - LR - SP900

Tire Model - RF - SP900

Tire Model - RR - SP900

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Left Running Board	Aftermarket	-	Acceptable
	Right Rear Bumper/Cover	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Photo - Dash	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Keys	Photo Only	-	-
	Front Metal Bumper Painted	Aftermarket	-	Acceptable
	Right Running Board	Aftermarket	-	Acceptable

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Wheel	Curb Rash	-	6 To 7 Inches
	Cab - Left	Multiple Scratches Heavy	-	7
	Right Cab Side	Multiple Scratches Heavy	-	6

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Front Wheel	Curb Rash	-	3 To 4 Inches
	Right Rear Wheel	Curb Rash	-	4 To 5 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.