



Approved CR

IAA Milwaukee
N70W25277 Indian Grass Lane
Branch No 521
Sussex, WI 53089
(262) 246-8822/(262) 246-4411
WHOLESALE ASSESSMENT ONLY

Make/Model: **2018 DODGE JOURNEY**
Sport Utility
Bodystyle/Series: **Vehicle SE AWD**
Color: **Black**
Mileage: **54,675 (Verified)**
Turn-in Mileage: **-**
VIN: **3C4PDDAG1JT491477**
Work Order/
Stock Number: **46315804**
Customer: **GSA Fleet Vehicle Sales**
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov
Client Stock #: **G612228V**
Vehicle Grade : **Grade 3.7**
Remarks: **-**
Announcements:

• WHEEL CORROSION

Certification : **-**
Req. Prev. Repair **-**
Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Flex Fuel	Cruise Control:	Yes
Engine Size:	3.6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /TAN	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Bench	Drive Type:	All Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes


Equipment


Additional Equipment:

Car Tire Size - RR 225 / 65 R 17	Car Tire Size - LF 225 / 65 R 17	Car Tire Size - RF 225 / 65 R 17
Car Tire Size - LR 225 / 65 R 17	LF Tires - 5/32 inch	LR Tires - 8/32 inch
RF Tires - 4/32 inch	RR Tires - 8/32 inch	Tire Brand - Front Left - FIRESTONE
Tire Brand - Front Right - FIRESTONE	Tire Brand - Rear Left - FIRESTONE	Tire Brand - Rear Right - FIRESTONE
Tire Model - RR - Destination Le	Tire Model - RF - Destination Le	Tire Model - LR - Destination Le
Tire Model - LF - Destination Le		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Rear Bumper	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Front Wheel	Corrosion	-	> 12 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Door	Chipped	-	2
	Right Rear Wheel	Corrosion	-	> 12 Inches
	Rear Bumper	Chipped	-	7
	Left Rear Wheel	Corrosion	-	> 12 Inches
	Left Front Wheel	Corrosion	-	> 12 Inches
	Left Front Wheel Cover	Curb Rash	-	1 To 2 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Front Wheel Cover	Curb Rash	-	3 To 4 Inches
	Front Bumper	Multiple Scratches Heavy	-	3
	Hood	Chipped	-	3

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.