



Approved CR

IAA Wilmington
415 Madeline Trask Drive
Branch No 733
Castle Hayne, NC 28429
(910) 675-2311/(910) 675-1619
WHOLESALE ASSESSMENT ONLY

Make/Model: **2023 DODGE
CHARGER**
4 Door Sedan
Bodystyle/Series: **POLICE
RWD**
Color: **Black**
Mileage: **27,360
(Verified)**
Turn-in Mileage: **-**
VIN: **2C3CDXAT7PH670867**
Work Order/
Stock Number: **46086826**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **G11A0897**
Vehicle Grade : **Grade 0.0**
Remarks: **-**
Announcements: **• Salvage**
Certification : **-**
Req. Prev. Repair **-**
Order: **-**



Drivable: No

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Gas	Cruise Control:	Yes
Engine Size:	5.7 L	Pwr Steering:	Yes
Roof:	Soft Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Leather/Cloth Interior /BLACK	Rear Defroster:	Yes
Airbag:	-	Tilt Steering:	Yes
Seats:	Power - Driver Only	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Hydraulic Brakes

Equipment


Additional Equipment:

Car Tire Size - LF 225 / 60 R 18	Car Tire Size - LR 225 / 60 R 18	Car Tire Size - RR 225 / 60 R 18
Car Tire Size - RF 225 / 60 R 18	LF Tires - 5/32 inch	LR Tires - 8/32 inch
RF Tires - 5/32 inch	RR Tires - 5/32 inch	Tire Brand - Front Left - GOODYEAR
Tire Brand - Front Right - GOODYEAR	Tire Brand - Rear Left - GOODYEAR	Tire Brand - Rear Right - GOODYEAR
Tire Model - RR - Eagle RS-A	Tire Model - RF - Eagle RS-A	Tire Model - LR - Eagle RS-A
Tire Model - LF - Eagle RS-A		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Fender	Photo Only	-	-
	Cargo Shelf	Aftermarket	-	Acceptable
	Rear Seats	Photo Only	-	-
	Core Support	Kinked	-	1/2 To 1 Inch
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 6	Photo Only	-	-
	Extra Photo 7	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Right Front Rail	Kinked	-	1 To 2 Inches

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Rail	Kinked	-	1 To 2 Inches
	Right Apron	Kinked	-	1 To 2 Inches
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Radiator	Cracked	-	Replacement Required
	Grille	Missing	-	Replacement Required
	Front Bumper	Missing	-	Replacement Required
	Left Head Lamp	Broken	-	Replacement Required

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Head Lamp	Missing	-	Replacement Required
	Hood	Severe Damage	-	Replacement Required
	Right Front Fender	Severe Damage	-	Replacement Required
	Windshield	Broken	-	Replacement Required
	Right Front Tire	Flat	-	Repair Required
	Left Front Fender	Severe Damage	-	Replacement Required

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Airbag - Front Right	Deployed	-	Replacement Required
	Roof Panel	Multiple Scratches Heavy	-	3
	Airbag - Front Left	Deployed	-	Replacement Required
	Left Knee Airbag	Deployed	-	Replacement Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.