



Approved CR

IAA Louisville North
891 Ballardsville Road
Branch No 669
Eminence, KY 40019
(502) 215-4804
WHOLESALE ASSESSMENT ONLY

Make/Model: **2015
CHEVROLET
EXPRESS
2500**

Bodystyle/Series: **Van LS**

Color: **Silver**

Mileage: **63,103
(Verified)**

Turn-in Mileage: **-**

VIN: **1GNWGPFG0F1270651**

Work Order/
Stock Number: **46234739**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G422216Z**

Vehicle Grade : **Grade 2.5**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Flex Fuel	Cruise Control:	Yes
Engine Size:	6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth/Vinyl /GRAY	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - RR 245 / 75 R 16

Car Tire Size - RF 245 / 75 R 16

Car Tire Size - LF 245 / 75 R 16

Car Tire Size - LR 245 / 75 R 16

LF Tires - 12/32 inch

LR Tires - 11/32 inch

RF Tires - 12/32 inch

RR Tires - 11/32 inch

Tire Brand - Front Left - FIRESTONE

Tire Brand - Front Right - FIRESTONE

Tire Brand - Rear Left - FIRESTONE

Tire Brand - Rear Right - FIRESTONE


Tire Model - LF - Transforce CV2

Tire Model - LR - Transforce CV2


Tire Model - RF - Transforce CV2

Tire Model - RR - Transforce CV2

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Extra Photo 7	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 5	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Odometer	Photo Only	-	-
	Warning - Tire Pressure	On	-	Unacceptable
	Extra Photo 4	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Cargo Door	Dent(S) W/No Paint Dmg	-	1 To 2 Inches
	Hood	Multiple Dents/Paint Damage	-	3
	Front Metal Bumper Painted	Chipped	-	4

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Wheel	Corrosion	-	2 To 3 Inches
	Right Qtr Panel	Multiple Dents/Paint Damage	-	3
	Right Rear Wheel	Curb Rash	-	1/2 To 1 Inch
	Rear Metal Bumper Painted	Multiple Scratches Heavy	-	4
	Right Rear Cargo Door	Multiple Dents/No Paint Damage	-	2
	Rear Ls Panel	Dent(S) W/ Paint Dmg	-	5 To 6 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Wheel	Curb Rash	-	3 To 4 Inches
	Left Front Door	Dent(S) W/No Paint Dmg	-	2 To 3 Inches
	Left Front Wheel	Corrosion	-	> 12 Inches
	Corner Panel	Chipped	-	1
	Left Dutch Cargo Door	Multiple Scratches Heavy	-	5

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.