Approved CR

IAA Salt Lake City
1800 South 1100 West
Branch No 342
Ogden, UT 84401-0258
(801) 399-2818/(801) 393-2325
WHOLESALE ASSESSMENT ONLY

Make/Model:	**2016 FORD F-350**
Bodystyle/Series:	**Regular Cab XL**
Color:	**White**
Mileage:	**48,613 (Verified)**
Turn-in Mileage:	-
VIN:	**1FDRF3B68GEC75570**
Work Order/ Stock Number:	**46371266**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G631712S**
Vehicle Grade :	**Grade 1.8**
Remarks:	-
Announcements:	-
Certification :	-
Req. Prev. Repair Order:	-



Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**8-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**6.2 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**No**
Radio:	-	Pwr Windows	**No**
Interior - Type/Color:	**Cloth/Vinyl /GRAY**	Rear Defroster:	**No**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Buckets**	Drive Type:	**4-Wheel Drive**
Seat Count:	-	Brakes:	**Disc**

Equipment

Additional Equipment:

Car Tire Size - LF 245 / 75 R 17	Car Tire Size - LR 245 / 75 R 17	Car Tire Size - RR 245 / 75 R 17
Car Tire Size - RF 245 / 75 R 17	LF Tires - 13/32 inch	LR Tires - 13/32 inch
RF Tires - 13/32 inch	RR Tires - 13/32 inch	Tire Brand - Front Left - IRONMAN
Tire Brand - Front Right - IRONMAN	Tire Brand - Rear Left - IRONMAN	Tire Brand - Rear Right - IRONMAN
Tire Model - LF - All Country A/T	Tire Model - RF - All Country A/T	Tire Model - LR - All Country A/T
Tire Model - RR - All Country A/T		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Pickup Bed	Aftermarket	-	Acceptable
	Left Rear Rail	Previous Repair	-	Acceptable
	Right Rear Rail	Previous Repair	-	Acceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Left Front Fender	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Metal Bumper Painted	Chipped	-	3
	Right Bed Side	Multiple Dents/Paint Damage	-	2
	Right Rear Wheel	Corrosion	-	> 12 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Metal Bumper Painted	Rust	-	2 To 3 Inches
	Tailgate	Peeling	-	2 To 3 Inches
	Left Rear Wheel	Corrosion	-	1 To 2 Inches
	Left Front Wheel	Corrosion	-	1 To 2 Inches
	Inside Bed	Peeling	-	> 12 Inches
	Right Front Door	Dent(S) W/No Paint Dmg	-	1/2 To 1 Inch

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Hood	Dent(S) W/ Paint Dmg	-	1 To 2 Inches
	Right Front Wheel	Corrosion	-	3 To 4 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.