



Approved CR

IAA Minneapolis/St. Paul
1280 Jackson Street
Branch No 526
St. Paul, MN 55117
(651) 488-0581/(651) 488-3644
WHOLESALE ASSESSMENT ONLY

Make/Model: **2016
CHEVROLET
SILVERADO
2500HD**

Bodystyle/Series: **Crew Cab
WT**

Color: **Gray**

Mileage: **39,552
(Verified)**

Turn-in Mileage: **-**

VIN: **1GC1KUEG3GF187821**

Work Order/
Stock Number: **46368957**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G631203S**

Vehicle Grade : **Grade 3.1**

Remarks: **-**

Announcements:

**• HAIL
DAMAGE**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Flex Fuel	Cruise Control:	Yes
Engine Size:	6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - RR 265 / 70 R 17

Car Tire Size - RF 265 / 70 R 17

Car Tire Size - LF 265 / 70 R 17

Car Tire Size - LR 265 / 70 R 17

LF Tires - 8/32 inch

LR Tires - 7/32 inch

RF Tires - 8/32 inch

RR Tires - 13/32 inch

Tire Brand - Front Left - BRIDGESTONE

Tire Brand - Front Right - BRIDGESTONE

Tire Brand - Rear Left - BRIDGESTONE

Tire Brand - Rear Right - BRIDGESTONE

Tire Model - LF - Duravis M700

Tire Model - LR - Duravis M700


Tire Model - RF - Duravis M700

Tire Model - RR - Duravis M700

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Warning - Tire Pressure	On	-	Unacceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Seat Cushion	Stained	-	Permanent
	Roof	Hail Damage	-	7
	Hood	Hail Damage	-	7
	Left Bed Side	Dent(S) W/ Paint Dmg	-	1/2 To 1 Inch
	Right Bed Side	Dent(S) W/ Paint Dmg	-	3 To 4 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.