



Approved CR

IAA Kansas City
2663 S 88th Street
Branch No 527
Kansas City, KS 66111
(913) 422-9303/(913) 422-7421
WHOLESALE ASSESSMENT ONLY

Make/Model: **2021
HYUNDAI
IONIQ
HYBRID**

Bodystyle/Series: **4 Door Hatch
Back BLUE**

Color: **Black**

Mileage: **99,940
(Verified)**

Turn-in Mileage: **-**

VIN: **KMHC65LC0MU249228**

Work Order/
Stock Number: **46290727**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G132863Y**

Vehicle Grade : **Grade 3.7**

Remarks: **-**

Announcements: **-**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	-	A/C:	No
Engine:	4-Cylinder Hybrid	Cruise Control:	Yes
Engine Size:	1.6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth/Vinyl /GRAY	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - LR 195 / 65 R 15	Car Tire Size - RR 195 / 65 R 15	Car Tire Size - RF 195 / 65 R 15
Car Tire Size - LF 195 / 65 R 15	LF Tires - 9/32 inch	LR Tires - 5/32 inch
RF Tires - 3/32 inch	RR Tires - 4/32 inch	Tire Brand - Front Left - IRONMAN
Tire Brand - Front Right - FIRESTONE	Tire Brand - Rear Left - FIRESTONE	Tire Brand - Rear Right - FIRESTONE
Tire Model - LF - Imove GEN2 As	Tire Model - LR - Weathergrip	Tire Model - RF - Weathergrip
Tire Model - RR - Weathergrip		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Front Bumper	Heavy Scratch	-	8 To 9 Inches
	Windshield	Star In Glass	-	1/2 To 1 Inch
	Rear Bumper	Heavy Scratch	-	1 To 2 Inches
	Right Front Tire	Worn	-	Replacement Required
	Right Front Seat Cushion	Stained	-	Permanent

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Roof	Dent(S) W/ Paint Dmg	-	2 To 3 Inches
	Left Qtr Panel	Heavy Scratch	-	1/2 To 1 Inch

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.