



Approved
CR

IAA Elkton
183 Zeitler Rd
Branch No 786
Elkton, MD 21921
(410) 695-4477
WHOLESALE ASSESSMENT ONLY

Make/Model: **2016 RAM
3500**
Bodystyle/Series: **Crew Cab
TRADESMAN**
Color: **Black**
Mileage: **24,289
(Verified)**
Turn-in Mileage: **-**
VIN: **3C63R3GT9GG322329**
Work Order/
Stock Number: **46433379**
Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**
Client Stock #: **g63-b1046**
Vehicle Grade : **Grade 2.7**
Remarks: **-**
Announcements: **-**
Certification : **-**
Req. Prev. Repair **-**
Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Gas	Cruise Control:	Yes
Engine Size:	5.7 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth/Vinyl /GRAY	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - RR 275 / 75 R 18	Car Tire Size - RF 275 / 75 R 18	Car Tire Size - LF 275 / 75 R 18
Car Tire Size - LR 275 / 75 R 18	LF Tires - 13/32 inch	LR Tires - 10/32 inch
RF Tires - 12/32 inch	RR Tires - 10/32 inch	Tire Brand - Front Left - NATIONAL
Tire Brand - Front Right - NATIONAL	Tire Brand - Rear Left - SUMITOMO	Tire Brand - Rear Right - SUMITOMO
Tire Model - LF - Commando A/T	Tire Model - LR - Encounter At	Tire Model - RF - Commando A/T
Tire Model - RR - Encounter At		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Extra Photo 6	Photo Only	-	-
	Left Front Fender	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Tailgate	Dent(S) W/ Paint Dmg	-	5 To 6 Inches
	Right Bed Side	Dent(S) W/ Paint Dmg	-	9 To 10 Inches
	Left Front Fender	Multiple Scratches Heavy	-	2
	Right Running Board	Rust	-	Severe Damage
	Left Bed Side	Multiple Scratches Heavy	-	10 Or More

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Front Metal Bumper Painted	Heavy Scratch	-	1/2 To 1 Inch
	Left Front Seat Cushion	Cut	-	5 To 6 Inches
	Steering Wheel	Worn	-	Replacement Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.