



Approved CR

IAA New Orleans East
6600 Almonaster Avenue
Branch No 432
New Orleans, LA 70126
(504) 240-2298/(504) 244-0883
WHOLESALE ASSESSMENT ONLY

Make/Model: **2016 FORD
F-450**

Bodystyle/Series: **Crew Cab XL**

Color: **White**

Mileage: **91,250
(Verified)**

Turn-in Mileage: **-**

VIN: **1FT8W4DT3GED31665**

Work Order/
Stock Number: **46390246**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G710435S**

Vehicle Grade : **Grade 2.9**

Remarks: **-**

Announcements:

- Active Codes
see IAA
Condition
Report

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Diesel	Cruise Control:	Yes
Engine Size:	6.7 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /GRAY	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Bench	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - LF 225 / 70 R 19

Car Tire Size - RR 225 / 70 R 19

Car Tire Size - LR 225 / 70 R 19

Car Tire Size - RF 225 / 70 R 19

LF Tires - 10/32 inch

LR Tires - 10/32 inch

RF Tires - 10/32 inch

RR Tires - 10/32 inch

Tire Brand - Front Left - CONTINENTAL

Tire Brand - Front Right - CONTINENTAL

Tire Brand - Rear Left - CONTINENTAL

Tire Brand - Rear Right - CONTINENTAL

Tire Model - LF - HSR

Tire Model - LR - HSR


Tire Model - RF - HSR

Tire Model - RR - HSR

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Fifth Wheel Trailer Hitch	Aftermarket	-	Acceptable

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Keys	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Inside Bed	Dent(S) W/ Paint Dmg	-	> 12 Inches
	Left Head Lamp	Faded	-	Repair Required
	Right Head Lamp	Faded	-	Repair Required
	Right Qtr Flare	Multiple Scratches Heavy	-	6
	Right Front Wheel	Corrosion	-	> 12 Inches
	Rear Metal Bumper Chrome	Dent(S) W/No Paint Dmg	-	> 12 Inches

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Qtr Flare	Multiple Scratches Heavy	-	4
	Left Bed Side	Dent(S) W/ Paint Dmg	-	2 To 3 Inches
	Left Front Wheel	Corrosion	-	9 To 10 Inches
	Windshield	Chipped	-	< 1/8 Inch

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.