



Approved CR

IAA Baton Rouge  
5978 Hwy 75  
Branch No 422  
Carville, LA 70721  
(225) 686-9197/(225) 686-8197  
WHOLESALE ASSESSMENT ONLY

Make/Model: **2021  
HYUNDAI  
ELANTRA**

Bodystyle/Series: **4 Door Sedan  
SE**

Color: **Blue**

Mileage: **146,067  
(Verified)**

Turn-in Mileage: **-**

VIN: **5NPLL4AG8MH050810**

Work Order/  
Stock Number: **46390489**

Customer: **GSA Fleet Vehicle Sales  
1800 F Street NW  
Washington, DC 20405  
fleetsalesupport@gsa.gov**

Client Stock #: **G133035Y**

Vehicle Grade : **Grade 2.4**

Remarks: **-**

Announcements: 

- Warning light  
see IAA  
Condition  
Report; crack  
in windshield

Certification : **-**

Req. Prev. Repair **-**

Order:



Drivable: Yes

### Equipment

|                        |                                           |                 |                          |
|------------------------|-------------------------------------------|-----------------|--------------------------|
| Transmission:          | <b>Continuously Variable Transmission</b> | A/C:            | <b>No</b>                |
| Engine:                | <b>4-Cylinder Gas</b>                     | Cruise Control: | <b>No</b>                |
| Engine Size:           | <b>2 L</b>                                | Pwr Steering:   | <b>No</b>                |
| Roof:                  | <b>-</b>                                  | Pwr Locks:      | <b>No</b>                |
| Radio:                 | <b>-</b>                                  | Pwr Windows     | <b>No</b>                |
| Interior - Type/Color: | <b>- /-</b>                               | Rear Defroster: | <b>No</b>                |
| Airbag:                | <b>-</b>                                  | Tilt Steering:  | <b>No</b>                |
| Seats:                 | <b>-</b>                                  | Drive Type:     | <b>Front Wheel Drive</b> |
| Seat Count:            | <b>-</b>                                  | Brakes:         | <b>-</b>                 |

## Equipment

### Additional Equipment:

Car Tire Size - RR 195 / 65 R 15

Car Tire Size - RF 195 / 65 R 15

Car Tire Size - LF 195 / 65 R 15

Car Tire Size - LR 195 / 65 R 15

LF Tires - 7/32 inch

LR Tires - 9/32 inch

RF Tires - 8/32 inch

RR Tires - 9/32 inch

Tire Brand - Front Left - SUREDRIVE

Tire Brand - Front Right - SUREDRIVE

Tire Brand - Rear Left - SUREDRIVE

Tire Brand - Rear Right - SUREDRIVE

Tire Model - LF - touring as

Tire Model - LR - touring as

Tire Model - RF - touring as

Tire Model - RR - touring as

## Non Chargeable Damages

| Photo                                                                               | Item                    | Damage     | Action | Severity     |
|-------------------------------------------------------------------------------------|-------------------------|------------|--------|--------------|
|    | Left Rear Bumper/Cover  | Photo Only | -      | -            |
|    | Right Rear Bumper/Cover | Photo Only | -      | -            |
|   | Photo - Dash            | Photo Only | -      | -            |
|  | Extra Photo 1           | Photo Only | -      | -            |
|  | Odometer                | Photo Only | -      | -            |
|  | Rear Seats              | Photo Only | -      | -            |
|  | Warning Light - Air Bag | On         | -      | Unacceptable |

### Non Chargeable Damages

| Photo                                                                               | Item                   | Damage     | Action | Severity |
|-------------------------------------------------------------------------------------|------------------------|------------|--------|----------|
|    | Photo - Vin/Id Sticker | Photo Only | -      | -        |
|    | Keys                   | Photo Only | -      | -        |
|    | Front Cover Center     | Photo Only | -      | -        |
|    | Right Side Panel       | Photo Only | -      | -        |
|    | Left Side Panel        | Photo Only | -      | -        |
|   | Instrument Panel       | Photo Only | -      | -        |
|  | Rear Bumper            | Photo Only | -      | -        |
|  | Extra Photo 2          | Photo Only | -      | -        |
|  | Extra Photo 3          | Photo Only | -      | -        |
|  | Right Front Fender     | Photo Only | -      | -        |
|  | Left Front Fender      | Photo Only | -      | -        |

### Non Chargeable Damages

| Photo                                                                             | Item   | Damage     | Action | Severity |
|-----------------------------------------------------------------------------------|--------|------------|--------|----------|
|  | Engine | Photo Only | -      | -        |

### Chargeable Damages

| Photo                                                                               | Item               | Damage                   | Action | Severity        |
|-------------------------------------------------------------------------------------|--------------------|--------------------------|--------|-----------------|
|    | Hood               | Bug Damage               | -      | Repair Required |
|    | Front Bumper       | Bug Damage               | -      | Repair Required |
|   | Right Front Fender | Multiple Scratches Light | -      | 3               |
|  | Right Rocker Panel | Multiple Scratches Heavy | -      | 3               |
|  | Right Qtr Panel    | Chipped                  | -      | 3               |

| Chargeable Damages                                                                  |                  |                      |        |               |
|-------------------------------------------------------------------------------------|------------------|----------------------|--------|---------------|
| Photo                                                                               | Item             | Damage               | Action | Severity      |
|    | Right Rear Wheel | Curb Rash            | -      | 3 To 4 Inches |
|    | Left Rear Wheel  | Curb Rash            | -      | 1 To 2 Inches |
|    | Left Front Wheel | Curb Rash            | -      | 2 To 3 Inches |
|   | Windshield       | Cracked              | -      | > 12 Inches   |
|  | Deck Lid         | Dent(S) W/ Paint Dmg | -      | > 12 Inches   |

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.