Approved
CR

IAA Spokane
3520 N Tschirley Rd
Branch No 322
Spokane, WA 99224
(509)891-2388/(855)631-9008
WHOLESALE ASSESSMENT ONLY



Make/Model:	**2018 RAM 1500**
Bodystyle/Series:	**- TRADESMAN 4X4 6`4 BOX**
Color:	**Blue**
Mileage:	**64,929 (Verified)**
Turn-in Mileage:	-
VIN:	**1C6RR7FG6JS297198**
Work Order/ Stock Number:	**46446578**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Washington, DC 20405 fleetsalessupport@gsa.gov
Client Stock #:	**G622812V**
Vehicle Grade :	**Grade 3.7**
Remarks:	-
Announcements:	• PARTS MAY BE MISSING • WINCH CONDITION UNKNOWN • REPAIRS OR REPLACEMENT MAY BE NEEDED
Certification :	-
Req. Prev. Repair Order:	-

Drivable: Yes

Equipment

Transmission:	**Automatic Transmission**	A/C:	**No**
Engine:	**6-Cylinder Flex Fuel**	Cruise Control:	**Yes**
Engine Size:	**3.6 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	-	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /GRAY**	Rear Defroster:	**Yes**
Airbag:	**Driver Side Air Bag**	Tilt Steering:	**Yes**
Seats:	**Bench**	Drive Type:	**4-Wheel Drive**

Equipment

Seat Count: -

Brakes: **Anti Lock Brakes**

Additional Equipment:

Car Tire Size - RR 265 / 70 R 17	Car Tire Size - RF 265 / 70 R 17	Car Tire Size - LF 265 / 70 R 17
Car Tire Size - LR 265 / 70 R 17	LF Tires - 6/32 inch	LR Tires - 7/32 inch
RF Tires - 6/32 inch	RR Tires - 7/32 inch	Tire Brand - Front Left - PIRELLI
Tire Brand - Front Right - PIRELLI	Tire Brand - Rear Left - PIRELLI	Tire Brand - Rear Right - PIRELLI
Tire Model - LF - Scorpion Atr	Tire Model - LR - Scorpion Atr	Tire Model - RF - Scorpion Atr
Tire Model - RR - Scorpion Atr		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 6	Photo Only	-	-
	Extra Photo 7	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Head Lamp	Faded	-	Repair Required
	Left Rear Door	Light Scratch	-	> 12 Inches
	Left Front Door	Heavy Scratch	-	> 12 Inches

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Tailgate	Dent(S) W/ Paint Dmg	-	1/2 To 1 Inch
	Roof	Light Scratch	-	> 12 Inches
	Right Rear Center Cap	Missing	-	Replacement Required
	Right Head Lamp	Faded	-	Repair Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.