



Approved CR

IAA Austin North
23010 Firefly Rd
Branch No 457
Florence, TX 76527
2549700575
mgr-austinnorth@iaai.com
WHOLESALE ASSESSMENT ONLY

2017
Make/Model: **CHEVROLET
EXPRESS
2500**
Bodystyle/Series: **Van LS**
Color: **White**
Mileage: **4,136
(Verified)**
Turn-in Mileage: -
VIN: **1GAWGEFG7H1266590**
Work Order/
Stock Number: **46350140**
Customer: GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov
Client Stock #: -
Vehicle Grade : **Grade 4.5**
Remarks: -
Announcements:

• Active Codes
see IAA
Condition
Report

Certification : -
Req. Prev. Repair -
Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	8-Cylinder Flex Fuel	Cruise Control:	Yes
Engine Size:	6 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /-	Rear Defroster:	No
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	4th	Drive Type:	Rear Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment


Additional Equipment:

Car Tire Size - LF 245 / 75 R 16	Car Tire Size - LR 245 / 75 R 16	Car Tire Size - RR 245 / 75 R 16
Car Tire Size - RF 245 / 75 R 16	LF Tires - 13/32 inch	LR Tires - 13/32 inch
RF Tires - 12/32 inch	RR Tires - 11/32 inch	Tire Brand - Front Left - BRIDGESTONE
Tire Brand - Front Right - BRIDGESTONE	Tire Brand - Rear Left - BRIDGESTONE	Tire Brand - Rear Right - BRIDGESTONE
Tire Model - RR - VSDT (V-Steel Super Deep Traction)	Tire Model - RF - VSDT (V-Steel Super Deep Traction)	Tire Model - LR - VSDT (V-Steel Super Deep Traction)
Tire Model - LF - VSDT (V-Steel Super Deep Traction)		

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Left Front Fender	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Right Front Fender	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Keys	Photo Only	-	-
	Engine	Photo Only	-	-
	Photo - Vin/Id Sticker	Photo Only	-	-

Chargeable Damages

Photo	Item	Damage	Action	Severity
-------	------	--------	--------	----------

Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Metal Bumper Painted	Heavy Scratch	-	1 To 2 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.