



Approved
CR

Perryopolis Auto Auction
3447 Pittsburgh Rd
PO Box 445
Perryopolis, PA 15473
724-736-4445/727-736-0466
jacob@perryautoauction.com
WHOLESALE ASSESSMENT ONLY

Make/Model: **2017
CHEVROLET
TAHOE**

Bodystyle/Series: **4 Door Sport
Utility Vehicle
K1500 LS**

Color: **BLUE**

Mileage: **47,098
(Verified, 6
digits)**

Turn-in Mileage: **-**

VIN: **1GNSKAEC1HR269571**

Work Order/
Stock Number: **000310981**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G62-0724U**

Vehicle Grade : **Grade 3.9**

Remarks: **-**



Announcements:

- DEFICIENCIES, WHEN KNOWN, HAVE BEEN NOTED IN THE ITEM DESCRIPTION; HOWEVER,
- THE ABSENCE OF ANY INDICATED DEFICIENCIES DOES NOT MEAN THERE ARE NONE

Certification : **Not Certified**

Req. Prev. Repair **-**

Order: **-**

Drivable: Yes

UniBody/Frame Damage: NO As Is 100K Miles: NO

Equipment

Transmission: **Automatic Transmission** A/C: **Yes**

Equipment

Engine:	8-Cylinder Gas	Cruise Control:	No
Engine Size:	5.3 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	No
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	- /BLACK	Rear Defroster:	No
Airbag:	Dual Air Bags	Tilt Steering:	Yes
Seats:	-	Drive Type:	4-Wheel Drive
Seat Count:	-	Brakes:	Power Brakes

Additional Equipment:

4 Wheel Drive	Air Conditioning	LF Tires - 11/32 inch
LR Tires - 11/32 inch	Power Brakes	Power Steering
Power Windows	RF Tires - 11/32 inch	RR Tires - 11/32 inch
Security System	Tilt Wheel	Tire Brand - Front Left - LF TIRE MFG Goodyear
Tire Brand - Front Right - RF TIRE MFG Goodyear	Tire Brand - Rear Left - LR TIRE MFG Goodyear	Tire Brand - Rear Right - RR TIRE MFG Goodyear

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Overall Picture - Odometer	Photo Only	Estimate Only	Unknown
	Photo - Front	Photo Only	Estimate Only	Unknown
	Photo - Right	Photo Only	Estimate Only	Unknown
	Trunk	Photo Only	Estimate Only	Unknown
	Photo - Left	Photo Only	Estimate Only	Unknown
	Photo - Wheel	Photo Only	Estimate Only	Unknown
	Miscellaneous	Photo Only	Estimate Only	Unknown

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Photo - Interior	Photo Only	Estimate Only	Unknown
	Vin Plate	Photo Only	Estimate Only	Unknown
	Overall Picture - Engine	Photo Only	Estimate Only	Unknown
	Hood	Faded	Report	Buffable
	Roof	Faded	Report	Buffable

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.