



Approved CR

IAA Chicago North
605 Healy Road
Branch No 514
East Dundee, IL 60118
(847) 426-5913/(847) 541-2114
WHOLESALE ASSESSMENT ONLY

Make/Model: **2020
HYUNDAI
ELANTRA**

Bodystyle/Series: **4 Door Sedan
SE**

Color: **Black**

Mileage: **24,731
(Verified)**

Turn-in Mileage: **-**

VIN: **5NPD74LF3LH606422**

Work Order/
Stock Number: **46375202**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G134579X**

Vehicle Grade : **Grade 4.0**

Remarks: **-**

Announcements: **• WHEEL
CORROSION**

Certification : **-**

Req. Prev. Repair **-**

Order: **-**



Drivable: Yes

Equipment

Transmission:	Continuously Variable Transmission	A/C:	No
Engine:	4-Cylinder Gas	Cruise Control:	Yes
Engine Size:	2 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth/Vinyl /GRAY	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Buckets	Drive Type:	Front Wheel Drive
Seat Count:	-	Brakes:	Disc

Equipment

Additional Equipment:

Car Tire Size - LF 195 / 65 R 15

Car Tire Size - LR 195 / 65 R 15

Car Tire Size - RR 195 / 65 R 15

Car Tire Size - RF 195 / 65 R 15

LF Tires - 6/32 inch

LR Tires - 5/32 inch

RF Tires - 6/32 inch

RR Tires - 5/32 inch

Tire Brand - Front Left - NEXEN

Tire Brand - Front Right - NEXEN

Tire Brand - Rear Left - NEXEN

Tire Brand - Rear Right - NEXEN


Tire Model - RR - Npriz AH8

Tire Model - RF - Npriz AH8

Tire Model - LR - Npriz AH8

Tire Model - LF - Npriz AH8

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Warning - Tire Pressure	On	-	Unacceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Rear Seats	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-
	Left Front Fender	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Rear Bumper	Chipped	-	2
	Left Rear Wheel	Corrosion	-	> 12 Inches
	Left Rear Door	Light Scratch	-	1 To 2 Inches
	Left Front Wheel	Corrosion	-	> 12 Inches
	Roof	Chipped	-	7
	Front Bumper	Chipped	-	3

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Right Rear Wheel Cover	Curb Rash	-	1 To 2 Inches

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.