



Approved CR

IAA Seattle
15801 110th Ave E
Branch No 327
Puyallup, WA 98374
(253)604-2300/(253)604-2390
WHOLESALE ASSESSMENT ONLY

Make/Model: **2017 FORD
TRANSIT
CONNECT**

Bodystyle/Series: **- XL**

Color: **Silver**

Mileage: **20,011
(Verified)**

Turn-in Mileage: **-**

VIN: **NM0GE9E79H1333603**

Work Order/
Stock Number: **46376274**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G413456U**

Vehicle Grade : **Grade 4.4**

Remarks: **-**

Announcements:

**• WARNING
INDICATOR
LIGHT ON
(SEE IAA
CONDITION
REPORT
FOR
DETAILS)**

Certification : **-**

Req. Prev. Repair **-**

Order:



Drivable: Yes

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	4-Cylinder Gas	Cruise Control:	Yes
Engine Size:	2.5 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	3rd	Drive Type:	Front Wheel Drive

Equipment

Seat Count: -

Brakes:

Disc

Additional Equipment:

Car Tire Size - RF 215 / 55 R 16

Car Tire Size - LR 215 / 55 R 16

Car Tire Size - RR 215 / 55 R 16

Car Tire Size - LF 215 / 55 R 16

LF Tires - 6/32 inch

LR Tires - 9/32 inch

RF Tires - 6/32 inch

RR Tires - 8/32 inch

Tire Brand - Front Left - CONTINENTAL

Tire Brand - Front Right - CONTINENTAL

Tire Brand - Rear Left - CONTINENTAL

Tire Brand - Rear Right - CONTINENTAL

Tire Model - RR - Contiprocontact

Tire Model - RF - Contiprocontact

Tire Model - LR - Contiprocontact

Tire Model - LF - Contiprocontact

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Rear Seats	Photo Only	-	-
	Warning - Tire Pressure	On	-	Unacceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-

Non Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Left Front Fender	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Odometer	Photo Only	-	-

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS

CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.