



Approved CR

IAA Southern NJ
250 Blackwood-Barnsboro Road
Branch No 612
Turnersville, NJ 08012
(856) 227-8760/(856) 227-8943
WHOLESALE ASSESSMENT ONLY

Make/Model: **2017 FORD
UTILITY
POLICE**

Bodystyle/Series: **Sport Utility
Vehicle -**

Color: **White**

Mileage: **65,322
(Verified)**

Turn-in Mileage: **-**

VIN: **1FM5K8AR3HGE26081**

Work Order/
Stock Number: **46341624**

Customer: **GSA Fleet Vehicle Sales
1800 F Street NW
Washington, DC 20405
fleetsalesupport@gsa.gov**

Client Stock #: **G620182V**

Vehicle Grade : **Grade 3.2**

Remarks: **-**

Announcements:

- Prior Law Enforcement / Uneconomical to Repair / Not driveable

Certification : **-**

Req. Prev. Repair **-**

Order:



Drivable: No

Equipment

Transmission:	Automatic Transmission	A/C:	No
Engine:	6-Cylinder Gas	Cruise Control:	Yes
Engine Size:	3.7 L	Pwr Steering:	Yes
Roof:	Hard Top	Pwr Locks:	Yes
Radio:	-	Pwr Windows	Yes
Interior - Type/Color:	Cloth Interior /BLACK	Rear Defroster:	Yes
Airbag:	Driver Side Air Bag	Tilt Steering:	Yes
Seats:	Bench	Drive Type:	All Wheel Drive
Seat Count:	-	Brakes:	Anti Lock Brakes

Equipment

Additional Equipment:

Car Tire Size - RR 245 / 55 R 18

Car Tire Size - RF 245 / 55 R 18

Car Tire Size - LF 245 / 55 R 18

Car Tire Size - LR 245 / 55 R 18

LF Tires - 6/32 inch

LR Tires - 7/32 inch

RF Tires - 5/32 inch

RR Tires - 4/32 inch

Tire Brand - Front Left - FALKEN

Tire Brand - Front Right - FALKEN

Tire Brand - Rear Left - FALKEN

Tire Brand - Rear Right - FALKEN

Tire Model - LF - Ziex ZE960 A/S

Tire Model - LR - Ziex ZE960 A/S


Tire Model - RF - Ziex ZE960 A/S

Tire Model - RR - Ziex ZE960 A/S

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Center Console	Aftermarket	-	Acceptable
	Rear Seats	Photo Only	-	-
	Odometer	Photo Only	-	-
	Extra Photo 1	Photo Only	-	-
	Photo - Dash	Photo Only	-	-
	Right Rear Bumper/Cover	Photo Only	-	-
	Left Rear Bumper/Cover	Photo Only	-	-

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Left Front Fender	Photo Only	-	-
[no photo]	Personally Identifiable Info	De-Identify	-	-
	Extra Photo 6	Photo Only	-	-
	Extra Photo 5	Photo Only	-	-
	Extra Photo 4	Photo Only	-	-
	Right Front Fender	Photo Only	-	-
	Extra Photo 3	Photo Only	-	-
	Extra Photo 2	Photo Only	-	-
	Rear Bumper	Photo Only	-	-
	Cargo Area	Aftermarket	-	Acceptable

Non Chargeable Damages

Photo	Item	Damage	Action	Severity
	Cargo Box	Aftermarket	-	Acceptable
	Aftermarket Accessory	Aftermarket	-	Acceptable
	Photo - Vin/Id Sticker	Photo Only	-	-
	Engine	Photo Only	-	-
	Keys	Photo Only	-	-
	Front Cover Center	Photo Only	-	-
	Right Side Panel	Photo Only	-	-
	Left Side Panel	Photo Only	-	-
	Instrument Panel	Photo Only	-	-

Chargeable Damages				
Photo	Item	Damage	Action	Severity
	Rear Bumper	Multiple Scratches Heavy	-	2
	Overall Vehicle	De-Identify	-	Removal Required

File Insurance Claim? - Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.