Approved CR

WHOLESALE ASSESSMENT ONLY

Make/Model:
Bodystyle/Series:
Color:
Mileage:
Turn-in Mileage:
VIN:
Work Order/
Stock Number:
Customer:
Client Stock #:
:
Remarks:
Announcements:
:
Req. Prev. Repair
Order:

## Equipment

Transmission:
Engine:
Engine Size:
Roof:
Radio:
Interior - Type/Color: /
Airbag:
Seats:
Seat Count:
Additional Equipment:

A/C:
Cruise Control:
Pwr Steering:
Pwr Locks:
Pwr Windows
Rear Defroster:
Tilt Steering:
Drive Type:
Brakes:

## Non Chargeable Damages

| Photo | Item | Damage | Comments | Parts | Labor | Labor Hours | Paint Hours | Estimate | Action | Severity |
|---|---|---|---|---|---|---|---|---|---|---|
|  | Rear Seats | Photo Only | - | - | - | - | - | $0.00 | - | - |

## Non Chargeable Damages

| Photo | Item | Damage | Comments | Parts | Labor | Labor Hours | Paint Hours | Estimate | Action | Severity |
|---|---|---|---|---|---|---|---|---|---|---|
|  | Photo - Vin/Id Sticker | Photo Only | - | - | - | - | - | $0.00 | - | - |
|  | Engine | Photo Only | - | - | - | - | - | $0.00 | - | - |
|  | Keys | Photo Only | - | - | - | - | - | $0.00 | - | - |
|  | Front Cover Center | Photo Only | - | - | - | - | - | $0.00 | - | - |
|  | Right Side Panel | Photo Only | - | - | - | - | - | $0.00 | - | - |
|  | Left Side Panel | Photo Only | - | - | - | - | - | $0.00 | - | - |
|  | Instrument Panel | Photo Only | - | - | - | - | - | $0.00 | - | - |
|  | Warning - Tire Pressure | On | - | $0.00 | $0.00 | - | - | $0.00 | - | Unacceptable |
|  | Rear Bumper | Photo Only | - | - | - | - | - | $0.00 | - | - |
|  | Right Front Fender | Photo Only | - | - | - | - | - | $0.00 | - | - |

## Non Chargeable Damages

| Photo | Item | Damage | Comments | Parts | Labor | Labor Hours | Paint Hours | Estimate | Action | Severity |
|---|---|---|---|---|---|---|---|---|---|---|
|  | Left Front Fender | Photo Only | - | - | - | - | - | $0.00 | - | - |
|  | Left Rear Bumper/Cover | Photo Only | - | - | - | - | - | $0.00 | - | - |
|  | Right Rear Bumper/Cover | Photo Only | - | - | - | - | - | $0.00 | - | - |
|  | Photo - Dash | Photo Only | - | - | - | - | - | $0.00 | - | - |
|  | Extra Photo 1 | Photo Only | - | - | - | - | - | $0.00 | - | - |
|  | Odometer | Photo Only | - | - | - | - | - | $0.00 | - | - |
| | | | | $0.00 (total) | $0.00 (total) | - | - | $0.00 (total) | | |

## Chargeable Damages

| Photo | Item | Damage | Comments | Parts | Labor | Labor Hours | Paint Hours | Estimate | Action | Severity |
|---|---|---|---|---|---|---|---|---|---|---|
|  | Front Bumper Cover Upper | Chipped | - | $0.00 | $433.00 | - | - | $433.00 | - | 3 |
|  | Hood | Chipped | - | $0.00 | $707.00 | - | - | $707.00 | - | 3 |

## Chargeable Damages

| Photo | Item | Damage | Comments | Parts | Labor | Labor Hours | Paint Hours | Estimate | Action | Severity |
|---|---|---|---|---|---|---|---|---|---|---|
|  | Right Front Wheel Cover | Peeling | - | $0.00 | $55.00 | - | - | $55.00 | - | 1/8 To 1/2 Inch |
|  | Right Rear Wheel Cover | Peeling | - | $0.00 | $55.00 | - | - | $55.00 | - | 2 To 3 Inches |
|  | Rear Bumper | Multiple Scratches Heavy | - | $0.00 | $289.00 | - | - | $289.00 | - | 5 |
| | | | | $0.00 (total) | $1,539.00 (total) | - | - | $1,539.00 (total) | | |

Additional Damages and Remarks:

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.

**No data was found**